



EFM32 Gecko EFM32LG Errata



This document contains information on the EFM32LG errata. The latest available revision of this device is revision F. Errata that have been resolved remain documented and can be referenced for previous revisions of this device. The device data sheet explains how to identify the chip revision, either from package marking or electronically. Errata effective date: November 2019.

1. Errata Summary

The table below lists all known errata for the EFM32LG and all unresolved errata in revision F of the EFM32LG.

Table 1.1. Errata Overview

Designator	Title/Problem	Work-around Exists	Exists on Revision:				
			B	C	D	E	F
ADC_E116	Offset in ADC Temperature Sensor Calibration Data	Yes	—	—	X	—	—
ADC_E117	TIMEBASE not wide enough	Yes	X	X	X	—	—
ADC_E118	Requirements for ADC_CLK > 7 MHz	Yes	X	X	X	X	X
AES_E101	BYTEORDER Does Not Work in Combination with DATASTART/XORSTART	Yes	X	X	X	—	—
AES_E102	AES_STATUS_RUNNING Set One Cycle Late With BYTEORDER Set	Yes	X	X	X	—	—
BURTC_E101	BURTC LPMODE Entry	No	X	X	X	—	—
BURTC_E102	BURTC_CNT Read Error	Yes	X	X	X	—	—
BU_E101	Backup Power Increased Power Consumption	Yes	X	—	—	—	—
BU_E102	EM4 GPIO Retention in Backup Mode	No	X	—	—	—	—
BU_E104	EM4 with Backup BODs	No	X	—	—	—	—
BU_E105	LFXO Missing Cycles During IOVDD Ramping	Yes	X	X	X	X	X
BU_E106	Current Leakage in Backup Mode	Yes	—	—	X	—	—
CMU_E108	LFxCLKEN Write	Yes	X	—	—	—	—
CMU_E110	LFXO Phase Shift	No	X	—	—	—	—
CMU_E111	LFXO Configuration Incorrect	Yes	X	X	—	—	—
CMU_E112	LFXO Boost Buffer Current Setting	Yes	—	—	X	—	—
CMU_E113	LFXO Startup at High Temperature	Yes	—	—	X	—	—
CMU_E114	Device Not Waking Up From EM2 When Using Pre-scaled Non-HFRCO Oscillator as HFCLK	Yes	X	X	X	X	X
CUR_E103	Increased EM2 Current	No	—	X	—	—	—
CUR_E104	Increased Current on AVDD2 (USB)	Yes	X	X	—	—	—
CUR_E105	Increased Current on AVDD2 (No USB)	Yes	X	X	—	—	—
DAC_E109	DAC Output Drift Over Lifetime	Yes	X	X	X	X	X
DI_E101	Flash Page Size	Yes	X	X	X	—	—
DMA_E101	EM2 with WFE and DMA	Yes	X	X	X	—	—
DMA_E102	2D Copy Corrupted by Ping-Pong or Scatter-Gather Operation on Another Channel	Yes	X	X	X	X	X
EBI_E101	EBI Masking Functionality	Yes	X	—	—	—	—
EBI_E102	EBI Access Fails	Yes	X	—	—	—	—
EBI_E103	Page Mode Read in D16A16ALE Mode	Yes	X	X	X	—	—

Designator	Title/Problem	Work-around Exists	Exists on Revision:				
			B	C	D	E	F
EMU_E105	Debug Unavailable During DMA Processing from EM2	Yes	X	—	—	—	—
EMU_E107	Interrupts During EM2 Entry	Yes	X	X	X	X	X
EMU_E110	Potential Hard Fault when Exiting EM2 or EM3	Yes	—	—	—	X	—
ETM_E101	ETM Trace Clock	Yes	X	—	—	—	—
GPIO_E101	GPIO Wakeup from EM4	Yes	X	—	—	—	—
LCD_E103	Indeterminate Animation Engine Start-Up	Yes	X	X	X	X	X
LCD_E104	Increased Current Draw when VLCD > VDDIO and LCD Pins are Used for GPIO	Yes	X	X	X	X	X
LES_E101	LESENSE and Schmitt Trigger	Yes	X	—	—	—	—
LES_E102	LESENSE and DAC CH1 Configuration	Yes	X	—	—	—	—
LES_E103	AUXHFRCO and LESENSE	Yes	—	—	X	—	—
LES_E104	LFPRESC Can Extend Channel Start-Up Delay	Yes	X	X	X	X	X
OPA_E101	OPAMP 2 Startup Rampup	No	X	—	—	—	—
PCNT_E102	PCNT Pulse Width Filtering Does Not Work	No	X	X	X	X	X
PRS_E101	Edge Detect on GPIO/ACMP	No	X	X	X	—	—
RMU_E101	POR Calibration Initialization Issue	Yes	—	—	—	X	—
RMU_E102	Regulator Output May Be 0 V After Supply Falls to Intermediate Voltage and Recovers	Yes	—	—	X	X	—
RMU_E103	Reset May Fail to Trigger During Supply Voltage Brownouts	Yes	—	—	X	X	—
TIMER_E103	Capture/Compare Output is Unreliable with RSSCOIST Enabled	No	X	X	X	X	X
USART_E112	USART AUTOTX Continues to Transmit Even With Full RX Buffer	No	X	X	X	—	—
USART_E113	IrDA Modulation and Transmission of PRS Input Data	Yes	X	X	X	X	X
USB_E101	USB DMA Transfers with Prescaled HFCLK	Yes	X	—	—	—	—
USB_E102	USB Datalines	No	X	—	—	—	—
USB_E103	HNP Sequence Fails if A-Device Connects After 3.4 ms	No	X	X	X	X	X
USB_E104	USB A-Device Delays the HNP Switch Back Process	No	X	X	X	X	X
USB_E105	B-Device as Host Driving K-J Pairs During Reset	No	X	X	X	X	X
USB_E106	USB Interrupts	Yes	X	—	—	—	—
USB_E107	Entry to EM4 Causes Temporary Leakage from VREG0	No	X	X	—	—	—
USB_E108	Floating DM/DP Pins Cause Leakage when USB is Disabled	Yes	X	X	—	—	—

Designator	Title/Problem	Work-around Exists	Exists on Revision:				
			B	C	D	E	F
USB_E109	Missing USB_GINTSTS.SESSREQINT Interrupt with USB_PCGCCTL.STOPPCLK = 1	Yes	X	X	X	X	X
USB_E110	Unexpected USB_HCx_INT.CHHLTD Interrupt	Yes	X	X	X	X	X

2. Current Errata Descriptions

2.1 ADC_E118 — Requirements for ADC_CLK > 7 MHz

Description of Errata
If operating the ADC_CLK at frequencies greater than 7 MHz, the ADC_BIASPROG register default value of 0x747 may not be sufficient to achieve the published missing codes performance specification.
Affected Conditions / Impacts
Devices operating the ADC_CLK at frequencies greater than 7 MHz while using the default ADC_BIASPROG value of 0x747 may experience performance outside data sheet limits.
Workaround
For systems requiring an ADC_CLK rate > 7 MHz, it may be necessary to increase the ADC's bias current components via the COMPBIAS, BIASPROG, and/or HALFBIAS bit fields in the ADC_BIASPROG register depending on a given application's ADC performance requirements.
Resolution
There is currently no resolution for this issue.

2.2 BU_E105 — LFXO Missing Cycles During IOVDD Ramping

Description of Errata
LFXO missing cycles during IOVDD ramping when used in combination with Backup mode.
Affected Conditions / Impacts
When IOVDD is ramped, the dc-level of the XTAL signal changes, resulting in missed LFXO cycles and possible glitches on the LFXO clock.
Workaround
Set PRESC in BURTC_CTRL to greater than 0 when ramping IOVDD in combination with Backup mode to avoid glitches on the LFXO clock.
Resolution
There is currently no resolution for this issue.

2.3 CMU_E114 — Device Not Waking Up From EM2 When Using Prescaled Non-HFRCO Oscillator as HFCLK

Description of Errata
Device not waking up from EM2 when using prescaled non-HFRCO oscillator as HFCLK.
Affected Conditions / Impacts
If the device is running from any prescaled oscillator other than HFRCO as HFCLK and HFRCO is disabled, the device will not wake up from EM2.
Workaround
Before entering EM2, clear CMU_CTRL_HFCLKDIV. Alternatively, enable HFRCO by setting CMU_OSCENCMD_HFRCOEN and wait until CMU_STATUS_HFRCORDY is set.
Resolution
There is currently no resolution for this issue.

2.4 DAC_E109 — DAC Output Drift Over Lifetime

Description of Errata
The voltage output of the DAC might drift over time.
Affected Conditions / Impacts
When the device is powered and the DAC is disabled, stress on an internal circuit node can cause the output voltage of the DAC to drift over time, and in some cases may violate the $V_{DACOFFSET}$ specification. If the DAC is always enabled while the device is powered, this condition cannot occur.
Workaround
Both in the startup initialization code and prior to disabling the DAC in application code, set the OPAnSHORT bit in DACn_OPACTRL to a '1' for the corresponding DAC(s) used by the application. This will prevent the output voltage drift over time effect.
Resolution
There is currently no resolution for this issue.

2.5 DMA_E102 — 2D Copy Corrupted by Ping-Pong or Scatter-Gather Operation on Another Channel

Description of Errata
When performing a 2D copy (rectangular copy) on one DMA channel, more data than is specified is occasionally transferred from the source buffer if another channel is being used in ping-pong or scatter-gather mode.
Affected Conditions / Impacts
The incorrect number of bytes is transferred during the 2D copy when there is corruption caused by concurrent ping-pong or scatter-gather operation. This would be most noticeable when 2D copy is used for moving a graphic image to a display but could cause problems in other use cases.
Workaround
Do not allow ping-pong or scatter-gather mode DMA transfers to occur concurrently with a 2D copy. If both types operations are required, interleave them such that the 2D copy is complete before enabling a channel in ping-pong or scatter-gather mode or vice versa.
Resolution
There is currently no resolution for this issue.

2.6 EMU_E107 — Interrupts During EM2 Entry

Description of Errata
An interrupt from a peripheral running from the high frequency clock that is received during EM2 entry will cause the EMU to ignore the SLEEPDEEP flag.
Affected Conditions / Impacts
During EM2 entry, the high frequency clocks that are disabled during EM2 will run for some clock cycles after WFI is issued to allow safe shutdown of the peripherals. If an enabled interrupt is requested from one of these non-EM2 peripherals during this shutdown period, the attempt to enter EM2 will fail, and the device will enter EM1 instead. As a result, the pending interrupt will immediately wake the device to EM0.
Workaround
Before entering EM2, disable all high frequency peripheral interrupts in the core.
Resolution
There is currently no resolution for this issue.

2.7 LCD_E103 — Indeterminate Animation Engine Start-Up

Description of Errata
The LCD controller animation engine starts counting based on when the writes to LCD_AREGA and LCD_AREGB occur in relation to the clock for the animation frame counter. Because the animation engine cannot know when the writes occur, it is not possible to know whether the A or B register will shift first, which can result in one of the registers shifting twice before the other shifts once.
Affected Conditions / Impacts
Animations that require specific sequencing may not start in the correct state such that frames are not displayed in the correct order.
Workaround
If animation sequences must be seen in a specific order, consider handling this in software instead of using the animation engine. If the purpose of the animation is to denote ongoing activity, use segments that can be cycled in a generic fashion such that the output achieves the desired effect without depending on a specific frame order.
Resolution
There is currently no resolution for this issue.

2.8 LCD_E104 — Increased Current Draw when VLCD > VDDIO and LCD Pins are Used for GPIO

Description of Errata
A leakage path to IOVDD exists when the LCD controller is configured to use the internally boosted or external power supply (LCD_DISPCTRL_VLCDSEL = VEXTBOOST) and VLCD > VDDIO. This is due to PMOS transistors in the LCD pin logic having their source/bulk terminals connected to the highest VDD (thus the LCD power supply when external/boost mode is used) while their gates are connected to IOVDD.
Affected Conditions / Impacts
Use of LCD pins for GPIO results in increased current draw when the LCD controller is configured to use the internally boosted or external supply (LCD_DISPCTRL_VLCDSEL = VEXTBOOST) and VLCD > VDDIO. This is particularly noticeable when the device is operating in EM2 as the LCD to IOVDD supply leakage can amount to tens of microamps. While the GPIO functionality of the LCD pins is not impaired, for certain applications, the increased current draw can be undesirable.
Workaround
Do not use LCD pins for GPIO functionality if the LCD controller is configured to use an external power supply or boost mode, and the resulting VLCD can be greater than the IOVDD supply.
Resolution
There is currently no resolution for this issue.

2.9 LES_E104 — LFPRESC Can Extend Channel Start-Up Delay

Description of Errata
Setting LESENSE_TIMCTRL_LFPRESC to a value other than DIV1 may delay channel start-up longer than the number of LFACLK _{LESENSE} clock cycles specified by LESENSE_TIMCTRL_STARTDLY.
Affected Conditions / Impacts
Delaying channel start-up delays the subsequent excitation and measurement phases and may have an impact on the data returned by the LESENSE.
Workaround
If a channel start-up delay is used (LESENSE_TIMCTRL_STARTDLY > 0), LESENSE_TIMCTRL_LFPRESC must be set to DIV1.
Resolution
There is currently no resolution for this issue.

2.10 PCNT_E102 — PCNT Pulse Width Filtering Does Not Work

Description of Errata
PCNT pulse width filtering does not work.
Affected Conditions / Impacts
The PCNT pulse width filter does not work as intended.
Workaround
Do not use the pulse width filter, i.e., ensure <code>FILT = 0</code> in <code>PCNTn_CTRL</code> .
Resolution
There is currently no resolution for this issue.

2.11 TIMER_E103 — Capture/Compare Output is Unreliable with RSSCOIST Enabled

Description of Errata
The TIMER capture/compare output is unreliable when <code>RSSCOIST</code> is enabled and the clock is prescaled.
Affected Conditions / Impacts
When <code>RSSCOIST</code> is set and <code>PRESC > 0</code> in <code>TIMERn_CTRL</code> , the capture/compare output value is not reliable.
Workaround
Do not use a prescaled clock, i.e., ensure <code>PRESC = 0</code> in <code>TIMERn_CTRL</code> when <code>RSSCOIST</code> is enabled.
Resolution
There is currently no resolution for this issue.

2.12 USART_E113 — IrDA Modulation and Transmission of PRS Input Data

Description of Errata
If the USART IrDA modulator is configured to accept input from a PRS channel, the incoming data stream will not be transmitted because the required clock from the baud rate generator is never enabled.
Affected Conditions / Impacts
It is not possible for the USART IrDA modulator to directly transmit data from a source other than the USART's own transmitter. The <code>USART_IRCTRL_IRPRSEN</code> bit should remain at its reset state of 0.
Workaround
Assuming the data to be sent via the PRS is also data that could be received by the EFM32/EFR32 USART, then the data can be received using the USART's PRS RX feature (<code>USART_INPUT_RXPRS = 1</code>), stored in RAM (e.g., using DMA), and then transmitted with IrDA mode enabled. In cases where IrDA operation is transmit-only, the PRS RX data can be received on the same USART doing the transmission. If IrDA operation is bidirectional, then another USART must be used to receive the PRS data.
If the data to be sent is in some other format (e.g., pulses from a timer output), then there is no direct way to transmit it using the IrDA modulator. It would be necessary to capture the data in some other way and reformat it as serial data timed according to the clock generated by the USART.
Resolution
There is currently no resolution for this issue.

2.13 USB_E103 — HNP Sequence Fails if A-Device Connects After 3.4 ms

Description of Errata
HNP Sequence fails if A-Device connects after 3.4 ms.
Affected Conditions / Impacts
The B-Device core only waits for up to 3.4 ms before signalling HNP fail and reverting back to Peripheral mode. Therefore, the HNP sequence fails if the A-Device connects after 3.4 ms.
Workaround
No known workaround.
Resolution
There is currently no resolution for this issue.

2.14 USB_E104 — USB A-Device Delays the HNP Switch Back Process

Description of Errata
The D+ line disconnects after 200 ms, delaying the HNP switch back process.
Affected Conditions / Impacts
The A-Device core delays the HNP switch back process. As per the USB-OTG 2.0 specification, the B-Device on the other side of the USB pipe either should wait for disconnect from the A-Device or should switch to Peripheral mode and wait for the A-Device to issue a USB reset. Hence, there is no significant impact on actual operation.
Workaround
No known workaround.
Resolution
There is currently no resolution for this issue.

2.15 USB_E105 — B-Device as Host Driving K-J Pairs During Reset

Description of Errata
The A-Device misinterprets the K-J pairs as Suspend after switching to High Speed mode.
Affected Conditions / Impacts
If the B-Device as Host on the other side of the USB pipe drives K-J pairs for more than 200 ms during USB reset, the A-Device core exits peripheral state, causing the HNP process to fail. There is no significant impact since normally the host drives USB reset for a shorter time than 200 ms.
Workaround
No known workaround.
Resolution
There is currently no resolution for this issue.

2.16 USB_E109 — Missing USB_GINTSTS.SESSREQINT Interrupt with USB_PCGCCTL.STOPPCLK = 1

Description of Errata
A Host-initiated Suspend, followed by a Host Disconnect and Host Connect, will not result in a SessReq interrupt.
Affected Conditions / Impacts
When USB_PCGCCTL.STOPPCLK is set and the device is acting as a B-peripheral, a Host-initiated Suspend, followed by a Host Disconnect and Host Connect, will not result in a SessReq interrupt.
Workaround
If this is an expected use-case, USB_PCGCCTL.STOPPCLK should not be set. USB_PCGCCTL.GATEHCLK can still be used to save power.
Resolution
There is currently no resolution for this issue.

2.17 USB_E110 — Unexpected USB_HCx_INT.CHHLTD Interrupt

Description of Errata
In some cases the USB_HCx_INT.CHHLTD interrupt might be incorrectly set.
Affected Conditions / Impacts
In some cases, an unexpected USB_HCx_INT.CHHLTD interrupt might be received from another endpoint that does not have the USB_HCx_CHAR.CHDIS, USB_HCx_INT.XACTERR, USB_HCx_INT.BBLERR, USB_HCx_INT.DATATGLERR, or USB_HCx_INT.XFERCOMPL interrupts enabled.
Workaround
If such an interrupt is received, the application must re-enable the channel for which it received the unexpected USB_HCx_INT.CHHLTD interrupt.
Resolution
There is currently no resolution for this issue.

3. Resolved Errata Descriptions

This section contains previous errata for EFM32LG devices.

For errata on the latest revision, refer to the beginning of this document. The device data sheet explains how to identify chip revision, either from package marking or electronically.

3.1 ADC_E116 — Offset in ADC Temperature Sensor Calibration Data

Description of Errata
The ADC temperature sensor calibration value stored in the Device Information (DI) Page has an offset.
Affected Conditions / Impacts
For devices with PROD_REV values of 16 or 17, the ADC0_TEMP_0_READ_1V25 register of the Device Information Page has an offset of 112. Using this value for calculating the absolute temperature gives an approximately 18 degrees too high value. Relative temperature measurements (temperature changes) are not affected by this offset.
Workaround
For devices with PROD_REV values of 16 or 17, use ADC0_TEMP_0_READ_1V25 - 112 instead of ADC0_TEMP_0_READ_1V25 when calculating the temperature.
Resolution
This issue is resolved in revision E devices.

3.2 ADC_E117 — TIMEBASE not wide enough

Description of Errata
For 48 MHz ADC clock, the ADC_CTRL_TIMEBASE is not wide enough.
Affected Conditions / Impacts
For ADC warm-up, the user is required to set the ADC_CTRL_TIMEBASE to the number of ADC clock cycles in 1 μ s. As this register is only 5 bits wide, it does not support frequencies above 32 MHz.
Workaround
If an ADC clock above 32 MHz is required, the acquisition time should be increased to also account for too short warmup-time.
Resolution
This issue is resolved in revision E devices.

3.3 AES_E101 — BYTEORDER Does Not Work in Combination with DATASTART/XORSTART

Description of Errata
When the BYTEORDER bit in AES_CTRL is set, an encryption or decryption should not be started through DATASTART or XORSTART.
Affected Conditions / Impacts
If BYTEORDER is used in combination with DATASTART or XORSTART, the AES data and key are interpreted in the wrong order.
Workaround
Do not use BYTEORDER in combination with DATASTART or XORSTART.
Resolution
This issue is resolved in revision E devices.

3.4 AES_E102 — AES_STATUS_RUNNING Set One Cycle Late With BYTEORDER Set

Description of Errata
When the BYTEORDER bit in AES_CTRL is set, AES_STATUS_RUNNING is set one cycle late.
Affected Conditions / Impacts
If BYTEORDER is used, it will take one cycle for the AES_STATUS_RUNNING flag to be set. This means that polling this status flag should be postponed at least one cycle after starting encryption/decryption.
Workaround
If polling the AES_STATUS_RUNNING is preferred, insert a No Operation assembly instruction (NOP()) before starting to poll the status flag.
Resolution
This issue is resolved in revision E devices.

3.5 BURTC_E101 — BURTC LPMODE Entry

Description of Errata
Entering LPMODE with LPCOMP=7 causes counter error.
Affected Conditions / Impacts
A counting error occurs if overflow on 7 LSBs happens when entering LPMODE with LPCOMP=7. This results in the counter value being 256 less than it should be after the error. The error accumulates.
Workaround
Avoid using LPMODE with LPCOMP=7.
Resolution
This issue is resolved in revision E devices.

3.6 BURTC_E102 — BURTC_CNT Read Error

Description of Errata
Software reads from BURTC_CNT might fail when LPMODE is activated.
Affected Conditions / Impacts
When LPMODE is active (i.e., BURTC_STATUS_LPMODEACT is high), software reads might result in the wrong value being read from BURTC_CNT.
Workaround
Before reading BURTC_CNT, disable LPMODE and wait for BURTC_STATUS_LPMODEACT to be cleared before reading BURTC_CNT.
Resolution
This issue is resolved in revision D devices.

3.7 BU_E101 — Backup Power Increased Power Consumption

Description of Errata
Additional current consumption on BU_VIN approximately 100uA when VDD_DREG is between 0.3 BU_VIN to 0.7 BU_VIN.
Affected Conditions / Impacts
Additional current consumption on BU_VIN approximately 100uA when VDD_DREG is between 0.3 BU_VIN to 0.7 BU_VIN.
Workaround
Avoid having VDD_DREG in between 0.3 BU_VIN to 0.7 BU_VIN.
Resolution
This issue is resolved in revision C devices.

3.8 BU_E102 — EM4 GPIO Retention in Backup Mode

Description of Errata
EM4 GPIO retention not shut off in backup mode.
Affected Conditions / Impacts
With GPIO retention enabled, GPIO pins will still drive in backup mode.
Workaround
Do not use EM4 GPIO retention in combination with backup mode.
Resolution
This issue is resolved in revision C devices.

3.9 BU_E104 — EM4 with Backup BODs

Description of Errata
EM4 with backup BODs does not trigger reset.
Affected Conditions / Impacts
EM4 with backup BODs does not trigger reset.
Workaround
Avoid using backup BODs when entering EM4.
Resolution
This issue is resolved in revision C devices.

3.10 BU_E106 — Current Leakage in Backup Mode

Description of Errata
In Backup mode, when $VDD > BU_VIN + 0.7$, current will leak from VDD.
Affected Conditions / Impacts
In Backup mode, when $VDD > BU_VIN + 0.7$, current will leak from VDD.
Workaround
To avoid leakage, exit Backup mode before VDD exceeds the voltage where the leakage starts by configuring the threshold in EMU_BUACT.
Resolution
This issue is resolved in revision E devices.

3.11 CMU_E108 — LFXCLKEN Write

Description of Errata
First write to LFXCLKEN can be missed.
Affected Conditions / Impacts
For devices with $PROD_REV < 15$, enabling the clock for LFA/LFB after reset and then immediately writing LFACLKEN/LFBCLKEN may cause the write to miss its effect.
Workaround
For devices with $PROD_REV < 15$, make sure CMU_SYNCBUSY is not set before writing LFACLKEN/LFBCLKEN. Can temporarily switch to HFCORECLKLEDIV2 to speed up clearing synchbusy.
Resolution
This issue is resolved in revision C devices.

3.12 CMU_E110 — LFXO Phase Shift

Description of Errata
Transients on pin D8 cause LFXO phase shift.
Affected Conditions / Impacts
Transients on pin D8 can give a temporary phase shift on LFXO. Frequency is unchanged.
Workaround
No known workaround.
Resolution
This issue is resolved in revision C devices.

3.13 CMU_E111 — LFXO Configuration Incorrect

Description of Errata
For devices with PROD_REV < 15, LFXOBUFCUR in CMU_CTRL is default 0 and LFXOBOOST in CMU_CTRL is default 1. However, these values are incorrect.
Affected Conditions / Impacts
For devices with PROD_REV < 15, LFXOBUFCUR in CMU_CTRL is default 0 and LFXOBOOST in CMU_CTRL is default 1. However, these values are incorrect.
Workaround
On devices with PROD_REV < 15, change LFXOBUFCUR to 1 and LFXOBOOST to 0.
Resolution
This issue is resolved in revision D devices.

3.14 CMU_E112 — LFXO Boost Buffer Current Setting

Description of Errata
LFXO boost buffer current must be disabled.
Affected Conditions / Impacts
LFXO will not work properly with LFXOBUFCUR in CMU_CTRL set.
Workaround
Do not set LFXOBUFCUR in CMU_CTRL.
Resolution
This issue is resolved in revision E devices.

3.15 CMU_E113 — LFXO Startup at High Temperature

Description of Errata
LFXO does not start at high temperature with default configuration.
Affected Conditions / Impacts
For devices with PROD_REV ≥ 16, the LFXO may have startup issues with low capacitance crystals when using the default LFXO configuration.
Workaround
Make this line of code part of your startup code, typically in the start of <code>main()</code> :
<pre>*((volatile uint32_t*) 0x400c80C0) = (*((volatile uint32_t*) 0x400c80C0) & ~(1<<6)) (1<<4);</pre>
Version v5.1.1 of the Gecko SDK will include this workaround for all affected device revisions.
Resolution
This issue is resolved in revision E devices.

3.16 CUR_E103 — Increased EM2 Current

Description of Errata
Increased consumption in EM2.
Affected Conditions / Impacts
Current consumption in EM2 and EM3 has two stable states, the normal state (1200 nA and 900 nA for EM2 and EM3 respectively) and an error state. In the error state, the current consumption in EM2 and EM3 is typically 4.5 μ A at 25 °C (manufacturing test limit is set to 7 μ A) but will increase with increased temperature. At 85 °C, the error state EM2 and EM3 current consumption is typically 25 μ A. It is unpredictable which state the device will go into on EM2/EM3 entry and it can also change state during operation.
Workaround
No known workaround.
Resolution
This issue is resolved in revision D devices.

3.17 CUR_E104 — Increased Current on AVDD2 (USB)

Description of Errata
On devices with USB, there can be increased current on AVDD2 related to VREG0.
Affected Conditions / Impacts
When VREG0 is floating or 0 V, a leakage can appear on AVDD2. This leakage is typically less than 10 μ A, but can also rise to around 300 μ A.
Workaround
Make sure VREG0 is always defined high when there is power on AVDD2. For bus-powered devices this is always the case, but for devices where the power on VREG0 can be lost during operation, e.g., a USB device where the USB phy is powered from VBUS when a master is attached, a 5 M Ω to VDD can help keep VREG0 defined.
Resolution
This issue is resolved in revision D devices.

3.18 CUR_E105 — Increased Current on AVDD2 (No USB)

Description of Errata
On devices without USB, an increased current on AVDD2 can appear due to a floating internal node. This leakage is typically less than 10 μ A, but can also rise to around 300 μ A. The leakage is present in all energy modes.
Affected Conditions / Impacts
An increased current on AVDD2 can appear due to a floating internal node. This leakage is typically less than 10 μ A, but can also rise to around 300 μ A. The leakage is present in all energy modes.
Workaround
To reduce this leakage to a few hundred nanoamps, set MODE10 and MODE11 in GPIO->P[5].MODEH to GPIO_P_MOD-EH_MODE10_PUSHPULL and GPIO_P_MODEH_MODE11_PUSHPULL respectively, and make sure bits 10 and 11 in GPIO->P[5].DOUT are set. To ensure GPIO->P[5] bits 10 and 11 stay set in EM4, set EM4RET in GPIO_CTRL to turn on GPIO retention before entering EM4.
Resolution
This issue is resolved in revision D devices.

3.19 DI_E101 — Flash Page Size

Description of Errata
The MEM_INFO_PAGE_SIZE value stored in the Device Information (DI) Page is incorrect.
Affected Conditions / Impacts
For devices with PROD_REV values lower than 18, the MEM_INFO_PAGE_SIZE register value in the Device Information Page is incorrect.
Workaround
Use fixed flash page size of 4 kB.
Resolution
This issue is resolved in revision D devices.

3.20 DMA_E101 — EM2 with WFE and DMA

Description of Errata
WFE does not work for the DMA in EM2.
Affected Conditions / Impacts
In EM2, when sleeping with WFE (Wait for Event), an interrupt from the DMA will not wake up the system.
Workaround
Use WFI (Wait for Interrupt) or EM1 instead.
Resolution
This issue is resolved in revision D devices.

3.21 EBI_E101 — EBI Masking Functionality

Description of Errata
EBI masking functionality is not limited to bank selected for TFT.
Affected Conditions / Impacts
EBI masking functionality is not limited to the bank selected for TFT (by BANKSEL field in EBI_TFTCTRL). When masking is enabled, a mask match can be generated and suppress writes to any bank.
Workaround
Disable masking when doing writes that should not be affected.
Resolution
This issue is resolved in revision C devices.

3.22 EBI_E102 — EBI Access Fails

Description of Errata
Certain EBI accesses via the Cortex and Debug interface do not work.
Affected Conditions / Impacts
Any access from the Cortex to the EBI not aligned to its size does not work. Also, only word accesses from the debug interface works.
Workaround
Make sure all accesses via the Cortex are aligned to its size, and that all debug accesses are word accesses.
Resolution
This issue is resolved in revision C devices.

3.23 EBI_E103 — Page Mode Read in D16A16ALE Mode

Description of Errata
Page mode read in D16A16ALE mode skips RDSETUP stage for page mode accesses.
Affected Conditions / Impacts
Page mode read in D16A16ALE mode skips RDSETUP stage for page mode accesses, making the read process go directly from ADDRSETUP to RDPA.
Workaround
To compensate for the missing hold time related to the ALE address latch, the HALFALE field in EBI_ADDRTIMING can be enabled providing a 1/2 cycle hold time.
Resolution
This issue is resolved in revision E devices.

3.24 EMU_E105 — Debug Unavailable During DMA Processing from EM2

Description of Errata
The debugger cannot access the system processing DMA request from EM2.
Affected Conditions / Impacts
DMA requests from the LEUART can trigger a DMA operation from EM2. While waiting for the DMA to fetch data from the respective peripheral, the debugger cannot access the system. If such a DMA request is not handled by the DMA controller, the system will keep waiting for it while denying debug access.
Workaround
Make sure DMA requests triggered from EM2 are handled.
Resolution
This issue is resolved in revision C devices.

3.25 EMU_E110 — Potential Hard Fault when Exiting EM2 or EM3

Description of Errata
The flash is powered down in EM2 and EM3 to save power. Some control registers in the flash can rarely enter an invalid state upon power-on, causing the first read of flash to be incorrect. If this occurs after exiting EM2 or EM3, the core attempts to fetch the interrupt address, but the value will be incorrect and may be invalid. In the case of an invalid value, the core will then jump to the hard fault handler for attempting to execute code from an invalid address. All subsequent reads from the flash are unaffected, and it is only the first flash read after exit from EM2 or EM3 that is potentially erroneous.
Affected Conditions / Impacts
When exiting EM2 or EM3, some devices may intermittently execute code incorrectly or enter the hard fault handler instead of entering the expected ISR associated with the wake source.
Workaround
To workaround this issue, move the interrupt vector table and interrupt service routines for EM2 or EM3 wake sources to RAM and perform a dummy read of the flash in the ISR. Additional information on the workaround and examples provided is available from the following Knowledge Base article URL: https://www.silabs.com/community/mcu/32-bit/knowledge-base.entry.html/2017/05/09/emu_e110_-_potential-i2Pn
Resolution
This issue has been resolved. Devices with a date code greater than or equal to 1742 will not have this issue.

3.26 ETM_E101 — ETM Trace Clock

Description of Errata
ETM Trace Clock needs to be delayed.
Affected Conditions / Impacts
ETM trace clock is out of phase making the data transition occur at the same time as the ETM trace clock transitions.
Workaround
ETM trace clock needs to be delayed between 10 ns and 1/4 of the trace clock period.
Resolution
This issue is resolved in revision C devices.

3.27 GPIO_E101 — GPIO Wakeup from EM4

Description of Errata
On GPIO wakeup from EM4, all cause bits for high-polarity wakeup pins are set.
Affected Conditions / Impacts
All EM4 wakeup cause bits for EM4 wakeup pins with high polarity are set on wakeup.
Workaround
Use low polarity if possible. For active high, slow changing inputs, a solution is to sample the inputs on wakeup.
Resolution
This issue is resolved in revision C devices.

3.28 LES_E101 — LESENSE and Schmitt Trigger

Description of Errata
Schmitt trigger cannot be disabled on pins used for sensor excitation
Affected Conditions / Impacts
When using LESENSE to excite a pin, the pin has to be configured in push-pull mode, which also enables the Schmitt trigger. If this pin has an input voltage somewhere in between $0.3 \times VDD$ and $0.7 \times VDD$, the Schmitt trigger will consume a considerable amount of current.
Workaround
Keep the input voltage to pins configured as push-pull outside the range $0.3 \times VDD$ to $0.7 \times VDD$ when LESENSE is not interacting with the connected sensor.
Resolution
This issue is resolved in revision C devices.

3.29 LES_E102 — LESENSE and DAC CH1 Configuration

Description of Errata
LESENSE cannot control DAC CH1 if DACCH0CONV in LESENSE_PERCTRL is set to DISABLE.
Affected Conditions / Impacts
LESENSE control of DAC CH1 cannot be enabled if DACCH0CONV in LESENSE_PERCTRL is set to DISABLE.
Workaround
Configure DACCH0CONV in LESENSE_PERCTRL to anything but DISABLE, this enables DAC CH1 to be controlled properly. If DAC CH0 is not to be used, set DACCH0OUT in LESENSE_PERCTRL to DISABLE. This will disable LESENSE control of DAC CH0, but still allow LESENSE to control DAC CH1.
Resolution
This issue is resolved in revision C devices.

3.30 LES_E103 — AUXHFRCO and LESENSE

Description of Errata
LESENSE will not work properly at low AUXHFRCO frequencies.
Affected Conditions / Impacts
LESENSE will not work properly when used with the AUXHFRCO running at the 1 or 7 MHz band.
Workaround
Do not use a AUXHFRCO frequency band of 1 or 7 MHz when used in combination with LESENSE.
Resolution
This issue is resolved in revision E devices.

3.31 OPA_E101 — OPAMP 2 Startup Rampup

Description of Errata
When OPA2 is started, the output ramp-up is constant independent of bias setting.
Affected Conditions / Impacts
When OPA2 is started the output ramp-up is constant independent of bias setting.
Workaround
No known workaround.
Resolution
This issue is resolved in revision C devices.

3.32 PRS_E101 — Edge Detect on GPIO/ACMP

Description of Errata
Edge detect on peripherals with asynchronous edges might be missed.
Affected Conditions / Impacts
When using edge detect in PRS on signals from ACMP, GPIO, RTC, LETIMER, LESENSE, VCMP, and BURTC, edges can be missed.
Workaround
Do not use edge detect on ACMP, GPIO, RTC, LETIMER, LESENSE, VCMP, and BURTC.
Resolution
This issue is resolved in revision E devices.

3.33 RMU_E101 — POR Calibration Initialization Issue

Description of Errata
Upon initial power-on, some devices may not be able to access flash memory above the 4 kB boundary, or some calibration registers on some devices may not be set to their factory calibration values.
Affected Conditions / Impacts
The list of affected devices can be found in the Knowledge Base (KB) article listed under Fix/Workaround. Some devices are sensitive to the power supply ramp during initial power-on. Specific ramp profiles on these devices can cause an intermittent issue resulting in one of two failure modes (A) or (B): A. Flash memory above the 4 kB boundary is inaccessible. Reads of the flash will return zeros. Write attempts will return an invalid address error code in the MSC_STATUS register. Code execution will behave as though the memory above 4 kB was filled with zeros until the device resets itself. B. Some parts of the calibration initialization process do not complete successfully. On USB devices, the USB voltage regulator does not get calibrated. Specific peripheral registers that may not be calibrated are as follows (not all registers apply to all devices): ADC0_CAL, IDAC_CAL, DAC0_CAL, DAC0_BIASPROG, DAC0_OPACTRL, and DAC0_OPAOFFSET. A SYSRESETREQ reset will clear either failure mode, and the device will behave normally until the next power-on event.
Workaround
Additional information including a software workaround is available from the following KB article URL: https://www.silabs.com/community/mcu/32-bit/knowledge-base.entry.html/2015/10/09/rmu_e101_-_por_calib-cEpZ
Resolution
This issue has been resolved. Devices with a date code and PROD_REV greater than or equal to 1539 and 0x96 respectively will not have this issue.

3.34 RMU_E102 — Regulator Output May Be 0 V After Supply Falls to Intermediate Voltage and Recovers

Description of Errata
Output of the on-chip regulator (DECOUPLE pin) may be approximately 0 V, and the device will not respond to a pin reset.
Affected Conditions / Impacts
The device supply voltage is specified as 1.98 V minimum. For certain supply waveforms, similar to disconnecting a battery, allowing the supply to decay to approximately 0.9 V (and stopping the decay at approximately 0.9 V), then reconnecting the battery, the output of the regulator (DECOUPLE pin) may be approximately 0 V. In this state, code will not execute, and the device will not respond to a pin reset. More information on this issue can be found at the following KB article URL: https://www.silabs.com/community/mcu/32-bit/knowledge-base.entry.html/2019/01/09/rmu_e102_por_bodres-AQh7
Workaround
Hold the RESETn pin logic low, starting before the supply is disconnected, and keep RESETn pin logic low until the supply reaches a valid voltage. If the DECOUPLE pin measures approximately 0 V, power cycle the supplies by pulling them all the way to 0 V before connecting supplies again.
Resolution
This issue is resolved in revision F devices.

3.35 RMU_E103 — Reset May Fail to Trigger During Supply Voltage Brownouts

Description of Errata
Reset may fail to trigger when the device supplies (AVDD_0, AVDD_2, VDD_DREG) fall to a voltage in the 1.25 - 1.45 V range.
Affected Conditions / Impacts
If the device supplies (AVDD_0, AVDD_2, VDD_DREG) fall to a voltage in the 1.25 - 1.45 V range, the device may fail to reset, allowing code execution while the supply voltage remains in the 1.25 - 1.45 V range. More information on this issue can be found at the following KB article URL: https://www.silabs.com/community/mcu/32-bit/knowledge-base.entry.html/2019/01/09/rmu_e103_por_bodres-N3MD
Workaround
Hold the RESETn pin in logic low, starting before the device supplies fall below 1.6 V, and keep the RESETn pin logic low until the device supplies reach a valid voltage again.
Resolution
This issue is resolved in revision F devices.

3.36 USART_E112 — USART AUTOTX Continues to Transmit Even With Full RX Buffer

Description of Errata
USART AUTOTX continues to transmit even with full RX buffer.
Affected Conditions / Impacts
When AUTOTX in USARTn_CTRL or AUTOTXEN in USARTn_TRIGCTRL is set, the USART will continue to transmit data even after the RX buffer is full. This may cause the RX buffer to overflow if the data is not read out in time.
Workaround
No known workaround.
Resolution
This issue is resolved in revision E devices.

3.37 USB_E101 — USB DMA Transfers with Prescaled HFCLK

Description of Errata
USB DMA transfers to flash fail when prescaling HFCLK.
Affected Conditions / Impacts
USB DMA transfers to flash may fail when prescaling HFCLK.
Workaround
Do not prescale HFCLK when using USB-DMA transfers to read from flash.
Resolution
This issue is resolved in revision C devices.

3.38 USB_E102 — USB Datalines

Description of Errata
USB datalines rise and fall time are slightly outside specification.
Affected Conditions / Impacts
USB datalines rise and fall time are slightly outside specification under worst case conditions. They may fail USB certification eye test depending on PCB layout.
Workaround
No known workaround.
Resolution
This issue is resolved in revision C devices.

3.39 USB_E106 — USB Interrupts

Description of Errata
USB interrupts have changed from being level triggered to edge triggered.
Affected Conditions / Impacts
USB interrupts are now triggered by signal edge rather than signal level.
Workaround
Make sure to handle edge triggered interrupts, rather than signal level interrupts.
Resolution
This issue is resolved in revision C devices.

3.40 USB_E107 — Entry to EM4 Causes Temporary Leakage from VREG0

Description of Errata
Entry to EM4 causes temporary leakage from VREG0.
Affected Conditions / Impacts
On transition from EM0 to EM4, a current leakage from VREG0 of up to 1 mA lasting a few seconds can occur.
Workaround
No known workaround.
Resolution
This issue is resolved in revision D devices.

3.41 USB_E108 — Floating DM/DP Pins Cause Leakage when USB is Disabled

Description of Errata
Floating DM/DP pins cause leakage when USB is disabled.
Affected Conditions / Impacts
When the USB_DM or USB_DP pins are floating while the USB PHY is disabled, a current in the order of a couple hundred μA may leak from USB_VREGO to VSS. This will not be an issue if there is no voltage applied to USB_VREGO, either externally or through the USB regulator.
Workaround
If there is no intention to use the USB module, e.g., the USB PHY is disabled, but there is still a voltage on USB_VREGO, make sure the USB_DM and USB_DP pins are defined. This can be done using GPIO or by defining them externally.
Resolution
This issue is resolved in revision D devices.

4. Revision History

Revision 1.40

November, 2019

- Updated to product revision F.
- Added [ADC_E118](#) and [LES_E104](#).
- Resolved [RMU_E102](#) and [RMU_E103](#).
- Migrated to new errata document format.

Revision 1.30

January, 2019

- Added [DMA_E102](#), [LCD_E103](#), [LCD_E104](#), [RMU_E102](#), [RMU_E103](#), and [USART_E113](#).
- Resolved [EMU_E110](#) and updated language to refer to both EM2 and EM3.
- Removed [ADC_E101](#), [CMU_E103](#), [CMU_E104](#), [CMU_E105](#), [MSC_E101](#), and [USART_E101](#) from revision history. These errata have never been present on Leopard Gecko.
- [RMU_E101](#) workaround URL updated.

Revision 1.20

April, 2017

- Added [EMU_E110](#).
- Updated errata formatting.
- Merged all errata documents for EFM32LG devices into one document.
- Merged errata history and errata into one document.

Revision 1.10

October, 2015

- Added [DAC_E109](#), [EMU_E107](#), [PCNT_E102](#), [RMU_E101](#), and [TIMER_E103](#).

Revision 1.00

October, 2014

- Initial release for EFM32LG360 and EFM32LG900 devices.

Revision 0.70

June, 2014

- Updated to product revision E.
- Removed errata that are not applicable to revision E.

Revision 0.60

August, 2013

- Added [ADC_E117](#), [AES_E102](#), [USB_E109](#), and [USB_E110](#).
- Updated disclaimer, trademark and contact information.

Revision 0.50

July, 2013

- Added [AES_E101](#), [BURTC_E102](#), [CMU_E114](#), and [DMA_E101](#).
- Updated errata naming convention.

Revision 0.40

June, 2012

- Added [DI_E101](#).

Revision 0.30

April, 2012

- Added [BU_E106](#) and [LES_E103](#).

Revision 0.20

January, 2012

- Added [CUR_E103](#), [CUR_E104](#), [CUR_E105](#), [USB_E107](#), and [USB_E108](#).
- Updated [PRS_E101](#).
- Removed Erratas not valid for chip revision.


Revision 0.10

November, 2011

- Initial preliminary release.

Silicon Labs

Simplicity Studio™4



Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/IoT



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support and Community
community.silabs.com

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

Trademark Information

Silicon Laboratories Inc.®, Silicon Laboratories®, Silicon Labs®, SiLabs® and the Silicon Labs logo®, Bluegiga®, Bluegiga Logo®, ClockBuilder®, CMEMS®, DSPLL®, EFM®, EFM32®, EFR, Ember®, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Ember®, EZLink®, EZRadio®, EZRadioPRO®, Gecko®, Gecko OS, Gecko OS Studio, ISOmodem®, Precision32®, ProSLIC®, Simplicity Studio®, SiPHY®, Telegesis, the Telegesis Logo®, USBXpress®, Zentri, the Zentri logo and Zentri DMS, Z-Wave®, and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

<http://www.silabs.com>