

## PIC16(L)F15325/45 Family Silicon Errata and Data Sheet Clarification

The PIC16(L)F15325/45 family devices that you have received conform functionally to the current Device Data Sheet (DS40001865D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC16(L)F15325/45 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A2**).

Data Sheet clarifications and corrections start on [page 6](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate website ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select **Programmer > Reconnect**.
  - b) For MPLAB X IDE, select **Window > Dashboard** and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16(L)F15325/45 silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

| Part Number  | Device ID <sup>(1)</sup> | Revision ID for Silicon Revision <sup>(2)</sup> |       |
|--------------|--------------------------|-------------------------------------------------|-------|
|              |                          | A1                                              | A2    |
| PIC16F15325  | 30C6h                    | 2001h                                           | 2002h |
| PIC16LF15325 | 30C7h                    | 2001h                                           | 2002h |
| PIC16F15345  | 30C8h                    | 2001h                                           | 2002h |
| PIC16LF15345 | 30C9h                    | 2001h                                           | 2002h |

**Note 1:** The Device IDs (DEVID and DEVREV) are located at addresses 8006h and 8005h, respectively. They are shown in hexadecimal in the format "DEVID DEVREV".

**2:** Refer to the "PIC16(L)F153XX Memory Programming Specification" (DS40001838) for detailed information on Device and Revision IDs for your specific device.

**TABLE 2: SILICON ISSUE SUMMARY**

| Module                                | Feature                                  | Item Number | Issue Summary                                                                                                                                                                                                                                                              | Affected Revisions |    |
|---------------------------------------|------------------------------------------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----|
|                                       |                                          |             |                                                                                                                                                                                                                                                                            | A1                 | A2 |
| Analog-to-Digital Converter (ADC)     | ADC Positive Voltage Reference           | 1.1         | Using FVR as the positive voltage reference to the ADC can cause missing codes in the conversion result.                                                                                                                                                                   | X                  | X  |
| Development Support                   | Data Breakpoints                         | 2.1         | Data breakpoints are not available on Banks 59 through 63.                                                                                                                                                                                                                 | X                  |    |
| Windowed Watchdog Timer (WWDT)        | Watchdog Timer Clock Source              | 3.1         | WWDT does not work with SOSC as the clock source.                                                                                                                                                                                                                          | X                  |    |
|                                       | Window Operation in DOZE mode            | 3.2         | Window feature of the WWDT does not operate correctly in DOZE mode.                                                                                                                                                                                                        | X                  | X  |
| I/O Ports                             | SMBus mode                               | 4.1         | SMBus levels are not functional on RB4 and RB6 PORT pins.                                                                                                                                                                                                                  | X                  |    |
|                                       | Slew Rate Control                        | 4.2         | Slew Rate Control feature does not exist on RB4 and RB6 PORT pins.                                                                                                                                                                                                         | X                  |    |
| Electrical Specifications             | SMBus VIL                                | 5.1         | The maximum VIL level changes when VDD is below 4.0V.                                                                                                                                                                                                                      | X                  |    |
|                                       | Fixed Voltage Reference (FVR) Accuracy   | 5.2         | Fixed Voltage Reference (FVR) output tolerance may be higher than specified at temperatures below -20°C.                                                                                                                                                                   | X                  | X  |
|                                       | Minimum VDD Specification for LF Devices | 5.3         | VDD Min for LF devices is 2.0V.                                                                                                                                                                                                                                            | X                  | X  |
| Master Synchronous Serial Port (MSSP) | SPI Slave mode                           | 6.1         | SSPBUF transmit shift register may be corrupted under certain conditions.                                                                                                                                                                                                  | X                  | X  |
| Nonvolatile Memory                    | WRERR Bit Operation                      | 7.1         | When performing a NVM high-voltage operation, if a Reset is issued in the middle of the operation, the WRERR bit is set. Then, if the user clears the WRERR bit and a Reset occurs again, this sets the WRERR bit because the internal latch has not been cleared earlier. | X                  | X  |
| Digital-to-Analog (DAC)               | Debug mode                               | 8.1         | FVR as the positive voltage source is not functional in Debug mode.                                                                                                                                                                                                        | X                  | X  |
| Reference Clock Output Module (CLKR)  | CLKR Output                              | 9.1         | First output pulse of Reference Clock Output modul is incorrect when CLKREN is enabled.                                                                                                                                                                                    | X                  | X  |

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A2).

### 1. Module: Analog-to-Digital Converter (ADC)

#### 1.1 ADC Positive Voltage Reference

Using the FVR as the positive voltage reference to the ADC can cause an increase in missing codes.

##### Work around

1. Increase the bit conversion time, known as TAD, to 8 us.
2. Use VDD as the positive voltage reference to the ADC.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

### 2. Module: Development Support

#### 2.1 Data Breakpoints

Data breakpoints are not available on Banks 59 through 63. Any breakpoints that are placed in Banks 59 through 63 will fail to be recognized.

##### Work around

None.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  |    |  |  |  |  |  |  |

### 3. Module: Windowed Watchdog Timer (WWDT)

#### 3.1 WWDT Clock Source Selection

When the WDTCS [2:0] bits of the WDTCON1 register are set to 'b010', selecting the Secondary Oscillator SOSC 32 kHz, as the clock source, the WWDT does not operate.

##### Work around

Use the LFINTOSC or MFINTOSC clock sources for the WWDT.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  |    |  |  |  |  |  |  |

### 3.2 Window Feature of the WWDT Does Not Operate Correctly in DOZE Mode

When the Windowed mode of operation is enabled in DOZE mode, a window violation error is issued even though the window is open and has been armed. This condition occurs only when the window size is set to a value other than 100% open.

##### Work around

1. Use the Windowed mode of operation in any other mode than DOZE. If disabling the DOZE mode is not an option, use the WWDT module without the window being enabled.
2. If the device is in DOZE mode, perform the arming process for the window in NORMAL mode, and return to the DOZE mode.
3. If there is an ISR in the application code, the arming within the window can be done inside the ISR with the ROI bit of the CPUDOZE register being set.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

### 4. Module: I/O Ports

#### 4.1 SMBus Mode

The SMBus signal levels are not available for the I<sup>2</sup>C functions of pins RB4 and RB6.

Standard ST and TTL levels are still available for these pins, which are configurable through the INLVLB register settings.

##### Work around

Use the Peripheral Pin Select (PPS) feature and move the required I<sup>2</sup>C functions to PORTC where the SMBus levels are still available.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  |    |  |  |  |  |  |  |

#### 4.2 Slew Rate Control

The Slew Rate Control feature is not available on pins RB4 and RB6.

##### Work around

Use other available PORT pins when slew rate control is required.

##### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  |    |  |  |  |  |  |  |

## 5. Module: Electrical Specifications

### 5.1 SMBus V<sub>IL</sub> Level

When the V<sub>DD</sub> voltage level supplied to the device is 4.0V and above, the maximum SMBus voltage level for the V<sub>IL</sub> parameter is 0.8V. When V<sub>DD</sub> drops below 4.0V, the maximum SMBus voltage level for V<sub>IL</sub> drops to 0.7V.

#### Work around

None.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  |    |  |  |  |  |  |  |

### 5.2 Fixed Voltage Reference (FVR) Accuracy

At temperatures below -20°C, the output voltage for the FVR may be greater than the level specified in the data sheet. This will apply to all three gain amplifier settings, (1X, 2X, 4X). The affected parameter numbers found in the data sheet are: FVR01 (1X gain setting), FVR02 (2X gain setting), and FVR03 (4X gain setting).

#### Work around

None.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

### 5.3 Minimum V<sub>DD</sub> Specification for LF Devices

Nonvolatile memory (NVM) access on LF devices may not work when operating at temperatures between -40°C and +25°C and V<sub>DD</sub> levels below 2.0V. V<sub>DD\_MIN</sub> for parameter (D002) is 2.0V for temperatures between -40°C and 25°C.

#### Work around

None.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

## 6. Module: Master Synchronous Serial Port (MSSP)

### 6.1 SSPBUF May Become Corrupted

When operating in SPI Slave mode, if the incoming SCK clock signal arrives during any of the conditions below, the SSPBUF transmit shift register may become corrupted. The transmitted slave byte cannot be ensured to be correct, and the state of the WCOL bit may or may not indicate a write collision.

These conditions include:

- A write to an SFR
- A write to RAM following an SFR read
- A write to RAM prior to an SFR read

#### Work around

##### **Method 1 (Interrupt Based Using $\overline{SS}$ ):**

1. Connect the  $\overline{SS}$  line to both the  $\overline{SS}$  input and either an INT or IOC input pin.
2. Enable INT or IOC interrupts (interrupt on falling edge if available, otherwise check that  $\overline{SS} == 0$  when the interrupt occurs).
3. Load SSPBUF with the data to be transmitted.
4. Continue program execution.
5. When the Interrupt Service Routine (ISR) is invoked, do either of the following:
  - Add a delay that ensures the first SCK clock will be complete, or
  - Poll SSPSTAT.BF (while(BF == 0)) and wait for the transmission/reception to complete.

Once either of these are complete, it is safe to return to program execution.

##### **Method 2 (Bit Polling Based Using $\overline{SS}$ ):**

1. Load SSPBUF with the data to be transmitted.
2. Poll the  $\overline{SS}$  line and wait for the  $\overline{SS}$  to go active (while(!PORTx.nSS == 0)).
3. When  $\overline{SS}$  is active ( $\overline{SS} == 0$ ), do either of the following:
  - Add a delay that ensures the first SCK clock will be complete, or
  - Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Once one of these two methods are complete, it is safe to return to program execution.

##### **Method 3 ( $\overline{SS}$ not Available):**

1. Load SSPBUF with the data to be transmitted.
2. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

## 7. Module: Nonvolatile Memory

### 7.1 WRERR Bit Operation

When a Reset is issued while an NVM high-voltage operation is in progress, the WRERR bit in the NVMCON1 register is set as expected. After clearing the WRERR bit, if a Reset reoccurs, the WRERR bit is set again regardless of whether an NVM operation is in progress or not. A successful write operation will clear the WRERR condition.

#### Work around

None.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

## 8. Module: Digital-to-Analog (DAC)

### 8.1 FVR as the Positive Voltage Source is Not Functional in Debug Mode

When using the DAC module while in Debug mode, and selecting the FVR as the positive voltage source, DAC1PSS = 10, the DAC is not functional and unexpected results can be seen on the output.

#### Work around

None.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

## 9. Module: Reference Clock Output Module (CLKR)

### 9.1 First Output Pulse of Reference Clock Output Module is Incorrect When CLKREN is Enabled

If CLKREN bit is set by the user, the number of input clock cycles taken to generate the reference clock output might vary by one cycle due to a race condition. This condition occurs only if LCx\_out or NCOx\_out are the inputs (CLKRCLK bits) to the CLKR module.

#### Work around

Ignore the first output pulse of the CLKR output signal.

#### Affected Silicon Revisions

| A1 | A2 |  |  |  |  |  |  |
|----|----|--|--|--|--|--|--|
| X  | X  |  |  |  |  |  |  |

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS40001865D):

**Note:** Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

### 1. Module: Table 36.3 Instruction Set Literal Operations

| LITERAL OPERATIONS |          |                             |          |           |             |             |             |          |  |
|--------------------|----------|-----------------------------|----------|-----------|-------------|-------------|-------------|----------|--|
| ADDLW              | k        | Add literal and W           | 1        | 11        | 1110        | kkkk        | kkkk        | C, DC, Z |  |
| ANDLW              | k        | AND literal with W          | 1        | 11        | 1001        | kkkk        | kkkk        | Z        |  |
| IORLW              | k        | Inclusive OR literal with W | 1        | 11        | 1000        | kkkk        | kkkk        | Z        |  |
| <b>MOVLB</b>       | <b>k</b> | <b>Move literal to BSR</b>  | <b>1</b> | <b>00</b> | <b>0001</b> | <b>01kk</b> | <b>kkkk</b> |          |  |
| MOVLP              | k        | Move literal to PCLATH      | 1        | 11        | 0001        | 1kkk        | kkkk        |          |  |
| MOVLW              | k        | Move literal to W           | 1        | 11        | 0000        | kkkk        | kkkk        |          |  |
| SUBLW              | k        | Subtract W from literal     | 1        | 11        | 1100        | kkkk        | kkkk        | C, DC, Z |  |
| XORLW              | k        | Exclusive OR literal with W | 1        | 11        | 1010        | kkkk        | kkkk        | Z        |  |

## APPENDIX A: DOCUMENT REVISION HISTORY

### **Rev B Document (07/2019)**

Updated Table 2, section 3. Module: Windowed Watchdog Timer (WWDT), section 5. Module: Electrical Specifications, added new section 6. Module: Master Synchronous Serial Port (MISSP), Added Section 8.1: Digital-to-Analog, Section 9.1: Reference Clock Output Module,

#### **Data Sheet Clarifications:**

Added Module 1: Table 36.3 Instruction Set

### **Rev A Document (12/2016)**

Initial release of this document.

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2016-2019, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-4763-4

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-72400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820