



MICROCHIP

PIC18F2331/2431/4331/4431

PIC18F2331/2431/4331/4431 Rev. A3 Silicon Errata

The PIC18F2331/2431/4331/4431 parts you have received conform functionally to the Device Data Sheet (DS39616), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F2331/2431/4331/4431 will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

All the issues listed here will be addressed in future revisions of the PIC18F2331/2431/4331/4431 silicon. **The following silicon errata apply only to PIC18F2331/2431/4331/4431 devices with these Device/Revision IDs:**

Part Number	Device ID	Revision ID
PIC18F2331	00 1000 111	00010
PIC18F2431	00 1000 110	00010
PIC18F4331	00 1000 101	00010
PIC18F4431	00 1000 100	00010

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in hexadecimal in the format "DEVID2 DEVID1".

1. Module: PCPWM

When the PCPWM is operated in Complementary mode with a non-zero dead-time value and the duty cycle results in an active-low time of less than 1 Tcy, the PWM generator will miss the rising edge for a new PWM period and the PWM output will alternate between one PWM period high and one PWM period low.

Work around

When in Complementary mode with a non-zero dead-time value, ensure that the active-low time will always be greater than 1 Tcy. In other words, when dead time is not equal to zero, ensure that:

$$\begin{aligned} \text{PDCH:PDCL} &< (4 * \text{PTPERH:PTPERL}) \\ \text{or} \\ \text{PDCH:PDCL} &> (4 * (\text{PTPERH:PTPERL} + 1)) \end{aligned}$$

Date Codes that pertain to this issue:

All engineering and production devices.

2. Module: PCPWM

When the PCPWM is operated in Center-Aligned mode with double updates and the duty cycle alternates on each update between a zero and non-zero value, an incorrect waveform is generated (the PWM output will alternate between one PWM period high and one PWM period low). If in Complementary mode, dead time will not be inserted properly.

Work around

Do not use zero duty cycle when in Center-Aligned mode with double updates. Instead of zero, set the duty cycle to a small, non-zero value.

Date Codes that pertain to this issue:

All engineering and production devices.

3. Module: PCPWM

When the PCPWM is operated in Center-Aligned mode with double updates and the duty cycle alternates on each update between a greater than 100% duty cycle and a non-zero value, an incorrect waveform is generated.

Work around

Do not use equal to or greater than 100% duty cycle when in Center-Aligned mode with double updates. Ensure that the maximum duty cycle value is always smaller than or equal to the PWM period, i.e., PDCH:PDCL $\leq$ (4 * (PTPERH:PTPERL)).

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F2331/2431/4331/4431

4. Module: PCPWM

If dead-time insertion is enabled and it is a non-zero value, glitches in the PWM output will occur under the following conditions:

1. When the PWM timer is stopped by clearing the PTEN bit.
2. When the duty cycle is changed to zero.

Work around

1. Before disabling the PWM timer, ensure that PORTB is set up to maintain a safe state of external hardware and that TRISB is set up to define the pins as outputs.
2. Do not use zero duty cycle when dead-time insertion is enabled. Instead of zero, set the duty cycle to a small, non-zero value (such as '1').

Date Codes that pertain to this issue:

All engineering and production devices.

5. Module: PCPWM

The PTMRH register will read as '00' or the last value written to it, even though the upper four bits of the PWM timer may be different. Writing to PTMRH will effect the upper four bits of the PWM timer when PTMRL is subsequently written. Although the PWM timer operates correctly, the double-buffer circuit does not transfer data to the PTMRH register from the upper four bits of the PWM timer.

Work around

PWM operation is not affected. Do not attempt to read PTMRH.

Date Codes that pertain to this issue:

All engineering and production devices.

6. Module: PCPWM

In Complementary mode with dead-time insertion, when using OVDCOND and OVDCONS to override the PWM outputs, dead time is not inserted correctly when the dead-time prescaler is Fosc/4, Fosc/8 or Fosc/16.

Work around

None. Use dead-time prescaler of Fosc/2 in these circumstances.

Date Codes that pertain to this issue:

All engineering and production devices.

7. Module: Core (DAW Instruction)

The DAW instruction may improperly clear the Carry bit (STATUS<0>) when executed.

Work around

Test the Carry bit state before executing the DAW instruction. If the Carry bit is set, increment the next higher byte to be added, using an instruction such as INCF SZ (this instruction does not affect any Status flags and will not overflow a BCD nibble). After the DAW instruction has been executed, process the Carry bit normally (see Example 1).

EXAMPLE 1: PROCESSING THE CARRY BIT DURING BCD ADDITIONS

```
MOVLW 0x80      ; .80 (BCD)
ADDLW 0x80      ; .80 (BCD)

BTFSC STATUS, C ; test C
INCFSZ byte2    ; inc next higher LSB
DAW
BTFSC STATUS, C ; test C
INCFSZ byte2    ; inc next higher LSB

This is repeated for each DAW instruction.
```

Date Codes that pertain to this issue:

All engineering and production devices.

8. Module: EUSART

Bit SENDB in the TXSTA register is not automatically cleared by hardware upon completion of transmission of a Sync Break.

Work around

Check the TRMT bit in TXSTA. If the TRMT bit is set, Break transmission is said to be complete.

9. Module: EUSART

If the transmitter is left enabled while the module is performing an auto-baud operation, an arbitrary data byte may get transmitted.

Work around

Clear TXEN bit (TXSTA<5>) before any auto-baud operation and set it after auto-baud is complete. Enable TXEN only when a data byte is to be transmitted. Care must be taken to ensure that the TX pin is pulled high, either through an external resistor, or by making the TX pin an output and writing '1' to it, to not disturb the transmit line.

10. Module: EUSART

This module may perform incorrect auto-baud calculation if the ABDEN (BAUDCTL<0>) bit was set while the receive pin was at a low level.

Work around

Wait for the RX pin to go high and then set the ABDEN bit.

11. Module: EUSART

In Asynchronous Receiver mode, the EUSART does not load the SPBRGH value after completion of auto-baud.

Work around

Do not enable the BRG16 (BAUDCTL<3>) bit.

If the BRG16 is in use, ensure that the auto-baud SPBRG value does not exceed the 8-bit value.

12. Module: EUSART

The CREN (RCSTA<4>) bit is cleared after every auto-baud operation.

Work around

Upon completion of auto-baud, manually set the CREN bit.

13. Module: EUSART

Writing to the USART/EUSART TXREG register faster than the baud rate in Synchronous mode will overwrite the previous value instead of double-buffering, as in Asynchronous mode.

Work around

Load the first character into TXREG and then wait for a TX interrupt, or check the TXIF bit before writing each additional character to TXREG.

14. Module: EUSART

The EUSART cannot receive asynchronous data at the four fastest baud rates (BRGH = 1, BRG16 = 1 and SPBRG < 4).

Work around

Use a slower baud rate or a faster system clock speed.

15. Module: HSADC

A ΔI_{AD} (parameter D026) of greater than 300 μA (for $V_{DD} = 3V$) is observed when the device is put into Sleep mode with the HSADC enabled (ADON = 1) without setting the GO/DONE bit so that at least one conversion is performed.

Observed ΔI_{AD} will increase in proportion to V_{DD} .

Work around

If no conversion will be done while in Sleep mode, disable the HSADC module by clearing the ADON bit before entering Sleep mode.

If power consumption is an issue for the application, do not put the part into Sleep mode with the HSADC enabled if no conversion is to be performed.

PIC18F2331/2431/4331/4431

REVISION HISTORY

Rev A Document (6/2004)

First revision of this document. Silicon issues 1-6 (PCPWM), 7 (Core – DAW Instruction) and 8-14 (EUSART) and Data Sheet Clarification issues 1 (Power-on Reset), 2 (Watchdog Timer), 3 (PWM Equations), 4 (DC Characteristics) and 5 (LVD Characteristics).

Rev B Document (12/2004)

Added Data Sheet Clarification issue 6 (28-Pin QFN Diagram).

Rev C Document (05/2005)

Added silicon issue 15 (HSADC). All Data Sheet Clarification issues were removed and placed into a separate Data Sheet Errata.

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELoQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

Amplab, FilterLab, Migratable Memory, MXDEV, MXLAB, PICMASTER, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, MPASM, MPLIB, MPLINK, MPSIM, PICKIT, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, rLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance and WiperLock are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2005, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona and Mountain View, California in October 2003. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Alpharetta, GA
Tel: 770-640-0034
Fax: 770-640-0307

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

San Jose

Mountain View, CA
Tel: 650-215-1444
Fax: 650-961-0286

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8676-6200
Fax: 86-28-8676-6599

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR

Tel: 852-2401-1200
Fax: 852-2401-3431

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Qingdao
Tel: 86-532-502-7355
Fax: 86-532-502-7205

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-2229-0061
Fax: 91-80-2229-0062

India - New Delhi
Tel: 91-11-5160-8631
Fax: 91-11-5160-8632

Japan - Kanagawa
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Penang
Tel: 011-604-646-8870
Fax: 011-604-646-5086

Philippines - Manila
Tel: 011-632-634-9065
Fax: 011-632-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Taiwan - Hsinchu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

EUROPE

Austria - Weis
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark - Ballerup
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Massy
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Ismaning
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

England - Berkshire
Tel: 44-118-921-5869
Fax: 44-118-921-5820