

PIC24FJ256DA210 Family Silicon Errata and Data Sheet Clarification

The PIC24FJ256DA210 family devices that you have received conform functionally to the current Device Data Sheet (DS39969B), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC24FJ256DA210 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A4).

Data Sheet clarifications and corrections start on [Page 7](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select Programmer > Reconnect.
 - b) For MPLAB X IDE, select Window > Dashboard and click the **Refresh Debug Tool Status** icon ().
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24FJ256DA210 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾	
		A3	A4
PIC24FJ256DA210	410Eh	03h	04h
PIC24FJ256DA206	410Ch		
PIC24FJ256DA110	410Fh		
PIC24FJ256DA106	410Dh		
PIC24FJ128DA210	410Ah		
PIC24FJ128DA206	4108h		
PIC24FJ128DA110	410Bh		
PIC24FJ128DA106	4109h		

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC24FJXXDA1/DA2/GB2/GA3/GC0 Families Flash Programming Specification" (DS39970) for detailed information on Device and Revision IDs for your specific device.

PIC24FJ256DA210 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾	
				A3	A4
Oscillator	Two-Speed Start-up	1.	Feature is not functional.	X	X
Resets	—	2.	POR flag also set on BOR and External Reset.	X	X
Enhanced PMP	—	3.	Write incompatibility with certain slave devices.	X	X
A/D Converter	—	4.	Module continues to draw current when disabled.	X	X
Interrupts	INTx	5.	External interrupts missed when writing to INTCON2	X	X
Output Compare	Cascaded Mode	6.	Some modes unavailable in Cascaded mode.	X	X
USB	Host Mode	7.	Low speed devices, when connected to a hub, will not work.	X	X
USB	Device and Host Modes	8.	ACTVIF wake-up behavior differs from previous documentation.	X	X
USB	OTG Mode	9.	VBUS comparators may trip at values outside of the required range for USB OTG operation.	X	X
USB	Device Mode	10.	EPSTALL bit behavior differs from previous documentation.	X	X
UART	Transmit	11.	A TX interrupt may occur before the data transmission is complete.	X	X
Output Compare	Interrupt	12.	Interrupt flag may precede the output pin change under certain circumstances.	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24FJ256DA210 FAMILY

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A4).

1. Module: Oscillator (Two-Speed Start-up)

Two-Speed Start-up is not functional. Leaving the IESO Configuration bit in its default state (Two-Speed Start-up is enabled) may result in unpredictable operation.

Work around

None. Always program the IESO Configuration bit to disable the feature (CW2<15> = 0).

Affected Silicon Revisions

A3	A4						
X	X						

2. Module: Resets

On Brown-out Resets and External (Master Clear) Resets, the POR bit may also become set. This may cause Brown-out and External Reset conditions to be indistinguishable from a Power-on Reset.

Work around

None.

Affected Silicon Revisions

A3	A4						
X	X						

3. Module: Enhanced PMP

The module is not write-compatible with slave devices that require data to be present before the write strobe is asserted. The module has no configuration provision to output data before asserting the write strobe.

Since most slave devices require valid input data to be present before the write strobe is deasserted, the significance of this issue is thought to be limited.

Work around

None.

Affected Silicon Revisions

A3	A4						
X	X						

4. Module: A/D Converter

Once the A/D module is enabled (AD1CON1<15> = 1), it may continue to draw extra current even if the module later is disabled (AD1CON1<15> = 0).

Work around

In addition to disabling the module through the ADON bit, set the corresponding PMD bit, ADC1MD (PMD1<0>), to power it down completely.

Affected Silicon Revisions

A3	A4						
X	X						

5. Module: Interrupts (INTx)

Writing to the INTCON2 register may cause an external interrupt event (inputs on INT0 through INT4) to be missed. This only happens when the interrupt event and the write event occur during the same clock cycle.

Work around

If this cannot be avoided, write the data intended for INTCON2 to any other register in the interrupt block of the SFR (addresses, 0080h to 00E0h); then write the data to INTCON2.

Be certain to write the data to a register not being actively used by the application, or to any of the interrupt flag registers, in order to avoid spurious interrupts. For example, if the interrupts controlled by IEC5 are not being used in the application, the code sequence would be:

```
IEC5 = 0x1E;  
INTCON2 = 0x1E;  
IEC5 = 0;
```

It is the user's responsibility to determine an appropriate register for the particular application.

Affected Silicon Revisions

A3	A4						
X	X						

PIC24FJ256DA210 FAMILY

6. Module: Output Compare (Cascaded Mode)

When 32-bit Cascaded mode is enabled (OCxCON2<8> = 1), these modes are unavailable:

- Single-Shot operations when OCM<2:0> (OCxCON1<2:0>) = 110 or 111, OCTRIG (OCxCON2<7>) = 1 and TRIGMODE (OCxCON1<3>) = 1.
- Synchronous modes when the SYNCSEL<4:0> bits (OCxCON2<4:0>) = 00000 and OCTRIG (OCxCON2<7>) = 0.

Work around

None.

Affected Silicon Revisions

A3	A4						
X	X						

7. Module: USB

While operating in Host mode and attached to a low-speed device through a full-speed USB hub, the host may persistently drive the bus to an SE0 state (both D+/D- are set as '0'), which would be interpreted as a bus Reset condition by the hub; or the host may persistently drive the bus to a J state, which would make the hub detach condition undetectable by the host.

Work around

Connect low-speed devices directly to the host USB port and not through a USB hub.

Affected Silicon Revisions

A3	A4						
X	X						

8. Module: USB (Device and Host Modes)

In previous literature for this module, the ACTVIF interrupt flag (U1OTGIR<4>) is described as being asserted, based on state changes detected on D+, D- or VBUS, when the microcontroller is in Sleep mode. In actual implementation, state changes on the RF3/USBID pin also cause the ACTVIF flag to be asserted.

As a result, logic input level changes on RF3/USBID may cause ACTVIF to be asserted, even in non-OTG applications that do not use the USBID function. This may cause the microcontroller to wake-up unexpectedly.

Work around

For On-The-Go (OTG) Based Applications: No work around is needed.

For non-OTG Device, Host or Dual Role Applications: If ACTVIF is used as a wake-up source, it is recommended that the application be designed so that RF3/USBID does not see any changes while the microcontroller is in a power-saving mode.

If RF3/USBID is not needed in the application, it is recommended to configure it as a digital output.

If the RF3/USBID pin is configured as a digital input, ensure that the signal provider does not change the pin state while ACTVIF is enabled as a wake-up source. If the pin is used as a general purpose input, which can change while in the USB suspend state, check the IDIF flag (U1OTGIR<7>) after waking up from an ACTVIF event to determine if the wake-up event was caused by a state change on RF3/USBID.

Affected Silicon Revisions

A3	A4						
X	X						

PIC24FJ256DA210 FAMILY

9. Module: USB (OTG Mode)

When using the on-chip VBUS comparators, the comparators may trip at values outside of the required range for USB OTG operation.

Work around

For Device Mode Operation: Use the SESVDIF interrupt flag and SESVD status bit for detection of VBUS, instead of the VBUSVDIF interrupt and VBUSVD status bit.

For OTG Operation: Use the External Comparator mode for proper level detection. This is enabled by setting the UVCMPDIS bit (U1CNFG2<1>).

Note that the External Comparator mode requires the application to include external comparators and logic to generate signals for the VCOMPST or VBUSVLD/SESSVLD/SESSEND digital input pins according to the bus conditions (Table 3). It is the user's responsibility to provide the appropriate circuit design for this application.

Affected Silicon Revisions

A3	A4						
X	X						

10. Module: USB (Device Mode)

In previous literature for this module, the EPSTALL bit (U1EPn<1>) is described as being an only stall status indicator bit in Device mode. In actual implementation, the EPSTALL bit functions as both a status and control bit.

If the EPSTALL bit for Endpoint 'n' is set (either by the SIE hardware or manually in firmware), both the IN and OUT endpoints, associated with the endpoint, will send STALL packets when the endpoint's UOWN bit (BDnSTAT<15>) is also set.

Work around

For Host Applications: No work around is needed, as hosts do not send STALL packets.

For Device Mode Applications: When it is necessary to stop sending STALL packets on an endpoint, clear the endpoint's respective BSTALL (BDnSTAT<10>) and EPSTALL bits. If the application firmware was developed based on one of the examples in the Microchip USB framework, this is already the default behavior of the USB stack firmware (except Version 2.8); no further work around is normally needed.

If a Device mode application was based upon Version 2.8 of the USB framework, and the application uses STALL packets on any of the application endpoints (1-15), it is suggested to update the application to the latest version.

Affected Silicon Revisions

A3	A4						
X	X						

TABLE 3: EXTERNAL COMPARATOR MODE INPUTS FOR VARIOUS VBus CONDITIONS

When UVCMPSEL = 0 :			
VCOMPST1	VCOMPST2	Bus Condition	
0	0	VBUS < VB_SESS_END	
1	0	VB_SESS_END < VBUS < VA_SESS_VLD	
0	1	VA_SESS_VLD < VBUS < VA_VBUS_VLD	
1	1	VBUS > VVBUS_VLD	
When UVCMPSEL = 1 :			
VBUSVLD	SESSVLD	SESSEND	Bus Condition
0	0	1	VBUS < VB_SESS_END
0	0	0	VB_SESS_END < VBUS < VA_SESS_VLD
0	1	0	VA_SESS_VLD < VBUS < VA_VBUS_VLD
1	1	0	VBUS > VVBUS_VLD

PIC24FJ256DA210 FAMILY

11. Module: UART (Transmit)

When using `UTXISEL<1:0> = 01` (interrupt when last character is shifted out of the Transmit Shift Register), and the final character is being shifted out through the Transmit Shift Register (TSR), the TX interrupt may occur before the final bit is shifted out.

Work around

If it is critical that the interrupt processing occurs only when all transmit operations are complete, after which, the following work around can be implemented:

Hold off the interrupt routine processing by adding a loop at the beginning of the routine that polls the Transmit Shift Register empty bit, as shown in [Example 1](#).

Affected Silicon Revisions

A3	A4						
X	X						

12. Module: Output Compare (Interrupt)

Under certain circumstances, an output compare match may cause the Output Compare Interrupt Flag (OCxIF) to become set prior to the Change-of-State (COS) of the OCx pin. This has been observed when all of the following are true:

- the module is in One-Shot mode (`OCM<2:0> = 001, 010 or 100`);
- one of the timer modules is being used as the time base; and
- a timer prescaler other than 1:1 is selected.

If the module is re-initialized by clearing `OCM<2:0>` after the one-shot compare, the OCx pin may not be driven as expected.

Work around

After OCxIF is set, allow an interval (in CPU cycles) of at least twice the prescaler factor to elapse before clearing `OCM<2:0>`. For example, for a prescaler value of 1:8, allow 16 CPU cycles to elapse after the interrupt.

Affected Silicon Revisions

A3	A4						
X	X						

EXAMPLE 1: DELAYING THE ISR BY POLLING THE TRMT BIT

```
// in UART2 initialization code
...
U2STABits.UTXISEL0 = 1;           // Set to generate TX interrupt when all
U2STABits.UTXISEL1 = 0;           // transmit operations are complete.
...

U2TXInterrupt(void)
{
    while(U2STABits.TRMT==0);      // wait for the transmit buffer to be empty
    ...                           // process interrupt
}
```

PIC24FJ256DA210 FAMILY

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS39969B):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Guidelines for Getting Started with 16-Bit Microcontrollers

Section 2.4 “Voltage Regulator Pins (ENVREG/DISVREG and VCAP/VDDCORE)” has been replaced with a new and more detailed section. The entire text follows:

2.4 Voltage Regulator Pins (ENVREG/DISVREG and VCAP/VDDCORE)

The on-chip voltage regulator enable pin must always be connected directly to a supply voltage.

Refer to **Section 27.2 “On-Chip Voltage Regulator”** for details on connecting and using the on-chip regulator.

When the regulator is enabled, a low-ESR ($< 5\Omega$) capacitor is required on the VCAP pin to stabilize the voltage regulator output voltage. The VCAP pin must not be connected to VDD and must use a capacitor of 10 μF connected to ground. The type can be ceramic or tantalum. Suitable examples of capacitors are shown in [Table 2-1](#). Capacitors with equivalent specifications can be used.

Designers may use [Figure 2-3](#) to evaluate ESR equivalence of candidate devices.

The placement of this capacitor should be close to VCAP. It is recommended that the trace length not exceed 0.25 inch (6 mm). Refer to **Section 30.0 “Electrical Characteristics”** for additional information.

FIGURE 2-3 FREQUENCY vs. ESR PERFORMANCE FOR SUGGESTED VCAP




TABLE 2-1 SUITABLE CAPACITOR EQUIVALENTS

Make	Part #	Nominal Capacitance	Base Tolerance	Rated Voltage	Temp. Range
TDK	C3216X7R1C106K	10 μF	$\pm 10\%$	16V	-55 to +125°C
TDK	C3216X5R1C106K	10 μF	$\pm 10\%$	16V	-55 to +85°C
Panasonic	ECJ-3YX1C106K	10 μF	$\pm 10\%$	16V	-55 to +125°C
Panasonic	ECJ-4YB1C106K	10 μF	$\pm 10\%$	16V	-55 to +85°C
Murata	GRM32DR71C106KA01L	10 μF	$\pm 10\%$	16V	-55 to +125°C
Murata	GRM31CR61C106KC31L	10 μF	$\pm 10\%$	16V	-55 to +85°C

PIC24FJ256DA210 FAMILY

2.4.1 CONSIDERATIONS FOR CERAMIC CAPACITORS

In recent years, large value, low-voltage, surface mount ceramic capacitors have become very cost effective in sizes up to a few tens of microfarad. The low-ESR, small physical size and other properties make ceramic capacitors very attractive in many types of applications.

Ceramic capacitors are suitable for use with the internal voltage regulator of this microcontroller. However, some care is needed in selecting the capacitor to ensure that it maintains sufficient capacitance over the intended operating range of the application.


Typical low-cost, 10 μF ceramic capacitors are available in X5R, X7R and Y5V dielectric ratings (other types are also available, but are less common). The initial tolerance specifications for these types of capacitors are often specified as $\pm 10\%$ to $\pm 20\%$ (X5R and X7R), or $-20\%/+80\%$ (Y5V). However, the effective capacitance that these capacitors provide in an application circuit will also vary based on additional factors, such as the applied DC bias voltage and the temperature. The total in-circuit tolerance is, therefore, much wider than the initial tolerance specification.

The X5R and X7R capacitors typically exhibit satisfactory temperature stability (ex: $\pm 15\%$ over a wide temperature range, but consult the manufacturer's data sheets for exact specifications). However, Y5V capacitors typically have extreme temperature tolerance specifications of $+22\%/-82\%$. Due to the extreme temperature tolerance, a 10 μF nominal rated Y5V type capacitor may not deliver enough total capacitance to meet minimum internal voltage regulator stability and transient response requirements. Therefore, Y5V capacitors are not recommended for use with the internal voltage regulator if the application must operate over a wide temperature range.

In addition to temperature tolerance, the effective capacitance of large value ceramic capacitors can vary substantially, based on the amount of DC voltage applied to the capacitor. This effect can be very significant, but is often overlooked or is not always documented.

A typical DC bias voltage vs. capacitance graph for 16V, 10V and 6.3V rated capacitors is shown in Figure 2-4.

FIGURE 2-4 DC BIAS VOLTAGE vs. CAPACITANCE CHARACTERISTICS



When selecting a ceramic capacitor to be used with the internal voltage regulator, it is suggested to select a high-voltage rating, so that the operating voltage is a small percentage of the maximum rated capacitor voltage. For example, choose a ceramic capacitor rated at 16V for the 1.8V V_{CAP} voltage. Suggested capacitors are shown in Table 2-1.

PIC24FJ256DA210 FAMILY

2. Module: Electrical Specifications


The “Absolute Maximum Ratings” listed on page 371 are amended by adding the following specification:

Voltage on V_{USB} with respect to V_{SS}.....
(V_{DDCORE} – 0.3V) to 4.0V

3. Module: Electrical Specifications (DC Characteristics)

Figure 30-1 (“PIC24FJ256DA210 Family Voltage-Frequency Graph”) is amended by adding an additional footnote. The updated figure is shown below (changes in **bold**; bold in original removed for clarity).

FIGURE 30-1: PIC24FJ256DA210 FAMILY VOLTAGE-FREQUENCY GRAPH (INDUSTRIAL)



Note 1: V_{CAP} (nominal On-Chip Regulator output voltage) = 1.8V.

2: When the USB module is enabled, V_{USB} should be provided at 3.0V to 3.6V. When the USB module is not enabled, the wider limits shaded in grey apply. The voltage on the V_{USB} pin should be maintained at (V_{DD} – 0.3V) or greater. Optionally, the pin may be left in a high-impedance state when the USB module is not in use, but doing so may result in higher I_{PD} currents than specified.

PIC24FJ256DA210 FAMILY

4. Module: Electrical Specifications (DC Characteristics)

Table 30-3 (“DC Characteristics: Temperature and Voltage Specifications”) is amended by adding a new specification, *V_{USB}*, and an explanatory footnote. The changes are shown below in **bold** (bold text in original removed for clarity).

5. Module: Enhanced Parallel Master Port (EPMP)

The following section is added to the end of the existing text of **Section 19.0 “Enhanced Parallel Master Port (EPMP)”**:

19.2 Alternate Master Cycle Period (TAM)

The Alternate Master Cycle Period (TAM) is a period of the synchronization used to generate the EPMP interface signals if the Alternate Master (Graphics Controller Module (GFX)) controls the EPMP I/Os directly. TAM is used when EPMP Bypass mode is selected, by setting the MSTSEL<1:0> bits (PMCON2<9:8>) to ‘11’.

The value of TAM is dependent on the setting of the G1CLKSEL bit (CLKDIV<4>). When G1CLKSEL = 1 (96 MHz graphics clock), TAM is 10.24 ns. When G1CLKSEL = 0 (48 MHz graphics clock), TAM is 20.48 ns.

**TABLE 30-3: DC CHARACTERISTICS: TEMPERATURE AND VOLTAGE SPECIFICATIONS
(PARTIAL REPRESENTATION)**

DC CHARACTERISTICS			Standard Operating Conditions: 2.0V to 3.6V (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for Industrial				
Param No.	Symbol	Characteristic	Min	Typ ⁽¹⁾	Max	Units	Conditions
Operating Voltage							
	V_{USB}	USB Supply Voltage	Greater of: 3.0 or (V_{DD} – 0.3V)	3.3	3.6	V	USB module enabled
			(V_{DD} – 0.3V)⁽³⁾	—	3.6	V	USB disabled, RG2/RG3 unused and externally pulled low or left in high-impedance state
			(V_{DD} – 0.3V)	V_{DD}	3.6	V	USB disabled, RG2/RG3 used as general purpose I/O

Note 1: Data in “Typ” column is at 3.3V, 25°C unless otherwise stated. Parameters are for design guidance only and are not tested.

2: This is the limit to which V_{DD} can be lowered without losing RAM data.

3: The **V_{USB}** pin may also be left in a high-impedance state under these conditions. However, if the voltage floats below (V_{DD} – 0.3V), this may result in higher I_{PD} currents than specified.

PIC24FJ256DA210 FAMILY

6. Module: Electrical Specifications (AC Characteristics)

Table 30-15 ("Internal RC Accuracy") is amended by dividing specification F20 into two temperature ranges with different accuracy ratings. The changes are shown below in **bold** (bold text and unchanged footnotes in original removed for clarity)

TABLE 30-15: INTERNAL RC ACCURACY

AC CHARACTERISTICS		Standard Operating Conditions: 2V to 3.6V (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for Industrial					
Param No.	Characteristic	Min	Typ	Max	Units	Conditions	
F20	FRC Accuracy@ 8 MHz	-1	—	1	%	$0^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$	$2\text{V} \leq V_{DD} \leq 3.6\text{V}$
		-1.5	—	1.5	%	$-40^{\circ}\text{C} \leq T_A < 0^{\circ}\text{C}$	$2\text{V} \leq V_{DD} \leq 3.6\text{V}$
F21	LPRC @ 31 kHz	-20	—	20	%	$-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$	V _{CAP} (on-chip regulator voltage output) = 1.8V

PIC24FJ256DA210 FAMILY

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (6/2010)

Initial release of this document; issued for revision A3. Includes silicon issues 1 (Oscillator – Two-Speed Start-up), 2 (Resets), 3 (Enhanced PMP), 4 (A/D), 5 (Interrupts – INTx), and 6 (Output Compare – Cascaded Mode).

Rev B Document (9/2010)

Revised silicon issue 4 (A/D Converter) to reflect updated definition of issues.

Added data sheet clarification issue 1 (Guidelines For Getting Started with 16-Bit Microcontrollers).

Rev C Document (1/2011)

Added silicon issue 7 (USB).

Rev D Document (6/2011)

Added silicon revision A4. Adds existing silicon issues 1 through 7 from revision A3 without changes. No new data sheet clarifications added. No issues removed.

Rev E Document (9/2011)

Added silicon issues 8 (USB – Device and Host Modes), 9 (USB – OTG Mode) and 10 (USB – Device Mode) to all revisions.

Added data sheet clarification issues 2, 3 and 4 (Electrical Characteristics).

Rev F Document (4/2012)

Added silicon issues 11 (UART – Transmit) and 12 (Output Compare – Interrupt) to all revisions.

Added data sheet clarification issue 5 (Enhanced Parallel Master Port (EPMP)).

Rev G Document (7/2013)

Added data sheet clarification issue 6 (Electrical Characteristics).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscent Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2010-2013, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-62077-314-7

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
= ISO/TS 16949 =

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-2819-3187
Fax: 86-571-2819-3189

China - Hong Kong SAR
Tel: 852-2943-5100
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8864-2200
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Osaka
Tel: 81-6-6152-7160
Fax: 81-6-6152-9310

Japan - Tokyo
Tel: 81-3-6880-3770
Fax: 81-3-6880-3771

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-213-7828
Fax: 886-7-330-9305

Taiwan - Taipei
Tel: 886-2-2508-8600
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

11/29/12