
SAM G55 Series Family Silicon Errata and Data Sheet Clarification

The SAM G55 Series family of devices that you have received conform functionally to the current Device Data Sheet (Atmel-11289F-ATARM-SAM-G55G-SAM-G55J-Datasheet_27-May-16), except for the anomalies described in this document.

New Silicon Errata Issues

Note: This document provides information on new errata issues for the SAM G55 Series family of devices. Refer to the current device data sheet for all pre-existing silicon errata issues.

1. Module: FLEXCOM in USART Mode

Reference: M32DOC-1852

When the Peripheral DMA Controller (PDC) is enabled, the USART Receiver Time Out Register (RTOR) read value is incorrect.

Work around

To read correctly, the USART RTOR value for all PDC channels and buffers must be disabled (transmitter and receiver) by writing the PDC Peripheral Transfer Control Register (PTCR) with the value of 0x010A0202.

Affected Silicon Revisions

A	B						
X	X						

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest revision of the device data sheet (Atmel-11289F-ATARM-SAM-G55G-SAM-G55J-Datasheet_27-May-16).

Corrections in tables and paragraphs are shown in **bold**. Where possible, the original bold text formatting has been removed for the clarity.

1. Module: Bootloader

Chapter 7 “Bootloader” in the data sheet has a new verbiage for the NRST line. The newly added text is shown in bold.

The SAM G55 devices ship with a factory-programmed bootloader in Flash. The Flash loader downloads code either through the SPI or through the TWI0.

The Bootloader mode is entered automatically on power-up if no valid firmware is detected in the Flash. A valid firmware is detected by performing a CRC on the content of the Flash. If the CRC is correct, the application is started. Otherwise, the Bootloader mode is entered.

Alternatively, the Bootloader mode can be forced by applying 10 low pulses of 1 ms on the NRST line (with a period of 10 ms maximum). When the Bootloader detects this sequence, it asserts the pin PA01 (NCHG) low as an acknowledge.

The Bootloader mode initializes the TWI0 in Slave Mode with the I²C address 0x26, and the SPI in Slave Mode, 8-bit data length, SPI Mode 1.

2. Module: System Configuration - CCFG_USBMR Register

In the current device data sheet section 15.9.7, the PLLFREQADJUST bit is missing from the register description. This bit occupies a bit offset of 4 as shown below.

PLLFREQADJUST: USB PLL Output Automatic Synchronization

0:USB PLL clock is not adjust

1:USB PLL output is automatically adjust at 48 MHz +/-0.25% whatever the internal 32 KHz accuracy.

3. Module: Clock Generator - CKGR_PLLAR Register

In the current device data sheet section 18.20.9, the MULA bit field for the CKGR_PLLAR register extends from bit 16 to bit 27. The corrected bit field extends from bit 16 to bit 28.

4. Module: Clock Generator - CKGR_PLLBR Register

In the current device data sheet, the MULB bit field for the CKGR_PLLBR register extends from bit field 16 to 26. The corrected bit field extended from 16 to 27.

5. Module: Clock Generator - PMC_PMMR Register

In the current device data sheet Section 18.20.32, the PLLA_MMAX bit field for the PMC_PMMR register extends from bit 0 to bit 10. The corrected bit field extends from bit 0 to bit 12.

6. Module: Clock Generator - PMC_PMMR Register


In the current device data sheet Section 18.20.32, the PLLB_MMAX bit field for the PMC_PMMR register extends from bit 16 to bit 26. The corrected bit field extends from bit 16 to bit 27.

7. Module: I²S Controller - I2SC_MR Register

In the current device data sheet Section 33.8.2, the table for the FORMAT bit is incorrect and lists left-justified format. This format is not supported for this device.

8. Module: USART - Transmitter Operations

Figure 30-6 is incorrect. The corrected figure is as shown below:



9. Module: USART - Multi-drop Mode

In the current device data sheet Section 30.6.3.6, the bit name SENTA is incorrect. The corrected name is SENDA.

10. Module: USART - ISO7816 Mode Overview

The last paragraph of the current device data sheet Section 30.6.4.1 has erroneous text. The corrected text is given in bold.

When operating in ISO7816, either in T = 0 or T = 1 modes, the character format is fixed. The configuration is 8 data bits and 1 or 2 stop bits, regardless of the values programmed in the Mode register fields CHRL, MODE9 and CHMODE. MSBF can be used to transmit LSB or MSB first. The Parity (PAR) bit can be used to transmit in normal or inverse mode. Refer to Section 31.7.3 "USART Mode Register" and "PAR: Parity Type".

11. Module: USART - US_RTOR Register

In the Section 30.7.20, the TimeOut (TO) bit information is incomplete, hence the following information has been added.

TimeOut (TO) value is 17 bits for USART, which supports all modes including LIN mode.

16 bits for USART, which supports all modes.

8 bits for USART, which does not support ISO7816.

12. Module: USART - US_LINMR Register

The following sentence in the current device data sheet Section 30.7.25 has an error and must be disregarded:

This register can only be written if the WPEN bit is cleared in the USART Write Protection Mode Register.

13. Module: Electrical Characteristics - Recommended Operating Conditions

Table 39-2 is updated to clarify the V_{DDIO_SLOPE} parameter. The new values are shown below.

Symbol	Parameter	Conditions	Min.	Typ.	Max.	Unit
V_{DDIO_SLOPE}	Slope on VDDIO	Single Supply, See Figure 5-2	1.5			V/ms
V_{DDIO_SLOPE}	Slope on VDDIO	Dual Supply, See Figure 5-3	7			V/ms

14. Module: USB Host Port (UHP): User Interface

The addresses listed for the UHP Registers are incorrect. The base address is **0x20400000**. All 23 register addresses must be read as 0x20400000 + the offset listed in Table 36.2.

Note: For example, when `ADC_MR.USEQ = 1` and a '1' is written to `CH2`, the channel defined in `ADC_SEQR1.USCH2` is part of the sequence of conversions.

15. Module: System I/O Lines -Table 9-6 “System I/O Configuration Pin List”

The default function after reset of PA21 and PA22 is I/O.

16. Module: Reset Controller (RSTC)

The `SYSC_WPMR` register is not present. References to that register must be ignored.

17. Module: Product Mapping

The offset listed for GPBR in Figure 6-1. SAM G55 Product Mapping must be 0x90.

18. Module: Supply Controller (SUPC)

In the device data sheet Section 25.5.2, the Supply Controller (SUPC) user interface erroneously lists offsets 0x20 through 0x2C as reserved. They are not part of the SUPC.

19. Module: General Purpose Backup Registers (GPBR)

The offset listed for `SYS_GPBR7` in Table 28-1. Register Mapping must be 0x1C.

20. Module: ADC Channel Status Register bit descriptions

The `CHx` bits in the `ADC_CHSR` register description must be as follows:

`CHx`: Channel x Status

0: The corresponding channel (or part of sequence, see `ADC_SEQR1.USCHx` field) is disabled.

1: The corresponding channel (or part of sequence, see `ADC_SEQR1.USCHx` field) is enabled.

APPENDIX A: REVISION HISTORY

Revision A Document (07/2019)

This is the initial released version of this document.

Revision B Document (01/2020)

This revision includes the following updates to Data Sheet Clarifications:

- 13. Module: Electrical Characteristics - Recommended Operating Conditions
- 14. Module: USB Host Port (UHP): User Interface
- 15. Module: System I/O Lines -Table 9-6 "System I/O Configuration Pin List"
- 16. Module: Reset Controller (RSTC)
- 17. Module: Product Mapping
- 18. Module: Supply Controller (SUPC)
- 19. Module: General Purpose Backup Registers (GPBR)
- The offset listed for SYS_GPBR7 in Table 28-1. Register Mapping must be 0x1C.

Revision C Document (04/2020)

This revision includes the addition of silicon Issue 1. Module: FLEXCOM in USART Mode Reference: M32DOC-1852.

SAM G55

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SSI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019-2020, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-5932-3

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199

Tel: 480-792-7200

Fax: 480-792-7277

Technical Support:

[http://www.microchip.com/
support](http://www.microchip.com/support)

Web Address:

www.microchip.com

Atlanta

Duluth, GA

Tel: 678-957-9614

Fax: 678-957-1455

Austin, TX

Tel: 512-257-3370

Boston

Westborough, MA

Tel: 774-760-0087

Fax: 774-760-0088

Chicago

Itasca, IL

Tel: 630-285-0071

Fax: 630-285-0075

Dallas

Addison, TX

Tel: 972-818-7423

Fax: 972-818-2924

Detroit

Novi, MI

Tel: 248-848-4000

Houston, TX

Tel: 281-894-5983

Indianapolis

Noblesville, IN

Tel: 317-773-8323

Fax: 317-773-5453

Tel: 317-536-2380

Los Angeles

Mission Viejo, CA

Tel: 949-462-9523

Fax: 949-462-9608

Tel: 951-273-7800

Raleigh, NC

Tel: 919-844-7510

New York, NY

Tel: 631-435-6000

San Jose, CA

Tel: 408-735-9110

Tel: 408-436-4270

Canada - Toronto

Tel: 905-695-1980

Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney

Tel: 61-2-9868-6733

China - Beijing

Tel: 86-10-8569-7000

China - Chengdu

Tel: 86-28-8665-5511

China - Chongqing

Tel: 86-23-8980-9588

China - Dongguan

Tel: 86-769-8702-9880

China - Guangzhou

Tel: 86-20-8755-8029

China - Hangzhou

Tel: 86-571-8792-8115

China - Hong Kong SAR

Tel: 852-2943-5100

China - Nanjing

Tel: 86-25-8473-2460

China - Qingdao

Tel: 86-532-8502-7355

China - Shanghai

Tel: 86-21-3326-8000

China - Shenyang

Tel: 86-24-2334-2829

China - Shenzhen

Tel: 86-755-8864-2200

China - Suzhou

Tel: 86-186-6233-1526

China - Wuhan

Tel: 86-27-5980-5300

China - Xian

Tel: 86-29-8833-7252

China - Xiamen

Tel: 86-592-2388138

China - Zhuhai

Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore

Tel: 91-80-3090-4444

India - New Delhi

Tel: 91-11-4160-8631

India - Pune

Tel: 91-20-4121-0141

Japan - Osaka

Tel: 81-6-6152-7160

Japan - Tokyo

Tel: 81-3-6880-3770

Korea - Daegu

Tel: 82-53-744-4301

Korea - Seoul

Tel: 82-2-554-7200

Malaysia - Kuala Lumpur

Tel: 60-3-7651-7906

Malaysia - Penang

Tel: 60-4-227-8870

Philippines - Manila

Tel: 63-2-634-9065

Singapore

Tel: 65-6334-8870

Taiwan - Hsin Chu

Tel: 886-3-577-8366

Taiwan - Kaohsiung

Tel: 886-7-213-7830

Taiwan - Taipei

Tel: 886-2-2508-8600

Thailand - Bangkok

Tel: 66-2-694-1351

Vietnam - Ho Chi Minh

Tel: 84-28-5448-2100

EUROPE

Austria - Wels

Tel: 43-7242-2244-39

Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4485-5910

Fax: 45-4485-2829

Finland - Espoo

Tel: 358-9-4520-820

France - Paris

Tel: 33-1-69-53-63-20

Fax: 33-1-69-30-90-79

Germany - Garching

Tel: 49-8931-9700

Germany - Haan

Tel: 49-2129-3766400

Germany - Heilbronn

Tel: 49-7131-72400

Germany - Karlsruhe

Tel: 49-721-625370

Germany - Munich

Tel: 49-89-627-144-0

Fax: 49-89-627-144-44

Germany - Rosenheim

Tel: 49-8031-354-560

Israel - Ra'anana

Tel: 972-9-744-7705

Italy - Milan

Tel: 39-0331-742611

Fax: 39-0331-466781

Italy - Padova

Tel: 39-049-7625286

Netherlands - Drunen

Tel: 31-416-690399

Fax: 31-416-690340

Norway - Trondheim

Tel: 47-7288-4388

Poland - Warsaw

Tel: 48-22-3325737

Romania - Bucharest

Tel: 40-21-407-87-50

Spain - Madrid

Tel: 34-91-708-08-90

Fax: 34-91-708-08-91

Sweden - Gothenberg

Tel: 46-31-704-60-40

Sweden - Stockholm

Tel: 46-8-5090-4654

UK - Wokingham

Tel: 44-118-921-5800

Fax: 44-118-921-5820