

# RT600

## Errata sheet RT600

Rev. 1.1 — May 27, 2020

Errata sheet

### Document information

Info	Content
<b>Keywords</b>	MIMXRT685SFFOB, MIMXRT685SFVKB, MIMXRT685SFAWBR, MIMXRT633SFVKB, MIMXRT633SFAWBR
<b>Abstract</b>	RT600 errata



**Revision history**

<b>Rev</b>	<b>Date</b>	<b>Description</b>
1.1	20200508	Added FlexSPI DLL lock status timing issue and addressed part marking.
1.0	20200213	Initial version.

**Contact information**

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

## 1. Product identification

The MIMXRT6xxSFAWBR WLCSP114 production samples has the following top-side package marking:

- First line: MRT6xxSF
- Second line: AW[R]R
- Third line: xxxxxx xx
- Fourth line: xxxxyyww
  - yyww: Date code with yy = year and ww = week
- Fifth line: xxx-yyy
- Sixth line: NXP

The MIMXRT6xxSFVKB VFBGA176 production samples has the following top-side package marking:

- First line: MRT6xxSFV
- Second line: K[R] xxxxxx
- Third line: xxyyww
- Fourth line: xxxxx
  - yyww: Date code with yy = year and ww = week

The MIMXRT685SFFOB FOWLP249 production samples has the following top-side package marking:

- First line: MRT6xxSFFOB
- Second line: xxxxxx
- Third line: xxxxxx
- Fourth line: xxxxyyww
  - yyww: Date code with yy = year and ww = week

**Table 1. Device revision table**

Revision identifier	Revision description [R]
B	Initial device revision

## 2. Errata overview

**Table 2. Functional problems table**

Functional problems	Short description	Revision identifier	Detailed description
FlexSPI	FlexSPI DLL lock status bit not accurate due to timing issue.	B	<a href="#">Section 3.1 “FlexSPI.1: FlexSPI DLL lock status bit not accurate due to timing issue”</a>

**Table 3. AC/DC deviations table**

AC/DC deviations	Short description	Product version(s)	Detailed description
n/a	n/a	n/a	n/a

**Table 4. Errata notes**

Errata notes	Short description	Revision identifier	Detailed description
n/a	n/a	n/a	n/a

### 3. Functional problems detail

---

#### 3.1 FlexSPI.1: FlexSPI DLL lock status bit not accurate due to timing issue

##### Introduction

Based on the sample clock source selection, the DLL control register (DLLxCR) can be used to set the delay line chain which allows a fixed number of delay cells or auto-adjusted to lock on a certain phase delay to the reference clock.

##### Problem

After configuring the DLL and setting the lock status bit, data may not be in sync if a read/write is performed immediately from a FLEXSPI based external flash due to timing issues.

##### Work-around

Add a delay time (100 NOP) again after the DLL lock status is set.

#### 4. AC/DC deviations detail

---

#### 5. Errata notes detail

---

No known errata.

## 6. Legal information

### 6.1 Definitions

**Draft** — The document is a draft version only. The content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included herein and shall have no liability for the consequences of use of such information.

### 6.2 Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the *Terms and conditions of commercial sale* of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or

malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

### 6.3 Trademarks

Notice: All referenced brands, product names, service names and trademarks are the property of their respective owners.

## 7. Contents

---

1	Product identification . . . . .	3
2	Errata overview . . . . .	4
3	Functional problems detail . . . . .	5
3.1	FlexSPI.1: FlexSPI DLL lock status bit not accurate due to timing issue . . . . .	5
	Introduction . . . . .	5
	Problem . . . . .	5
	Work-around . . . . .	5
4	AC/DC deviations detail . . . . .	6
5	Errata notes detail . . . . .	6
6	Legal information. . . . .	7
6.1	Definitions . . . . .	7
6.2	Disclaimers . . . . .	7
6.3	Trademarks . . . . .	7
7	Contents . . . . .	8

---

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

---

© NXP B.V. 2020.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: May 27, 2020

Document identifier: RT600 B