

Product Change Notice

Issue Date: September 18, 2019

Change Type:

Add SPIL Taiwan as Bump supplier

Parts Affected:

BCM56980B0KFSBG
BCM56982B0KFSBG
BCM56983B0KFSBG
BCM56984B0KFSBG

Description and Extent of Change:

Additional CuP Bump supplier - SPIL TAIWAN


Reasons for Change:

- Adding bump supplier. Broadcom reserves the right to manage supplier.
- The construction of the bump is identical
- SPIL Taiwan has internally qualified the direct CuP bumping and in volume production.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to insure normal parametric distribution, consistent electrical performance, and reliability.

Box label will be changed to identify correct bump supplier:



Effective Date of Change:

Product shipments using this change will be effective 90 days from the issue date.



Qualification Data:

Bump Type	OSAT	Bump Supplier	Package Type	MSL3	HTSL 150C 1000 Hours	TCT Cond B 1000 Cycles	UHAST 96 Hours
CuP	SPIL TAIWAN	SPIL TAIWAN	FCBGA+HS	PASS	0/77	0/77	0/77

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.