



Customer Information Notification

202001001I

Issue Date: 18-Mar-2020

Effective Date: 19-Mar-2020

Here's your personalized quality information concerning products Digi-Key purchased from NXP.
For detailed information we invite you to view this notification online

This notice is NXP Company Proprietary.



QUALITY

Change Category

☐ Wafer Fab Process

☐ Wafer Fab Materials

☐ Wafer Fab Location

☐ Firmware

☐ Assembly Process

☐ Assembly Materials

☐ Assembly Location

☐ Product Marking

☐ Mechanical Specification

☐ Packing/Shipping/Labeling

☐ Test Location

☐ Test Process

☐ Test Equipment

☐ Design

☒ Errata

☐ Electrical spec./Test coverage

☒ Other - Data Sheet Update for correction and clarification

i.MXRT1060 Data Sheet Rev 0.2 and Errata Rev 1.1 Updates

Description

NXP Semiconductors announces errata update to revision 1.1 and data sheet update to revision 0.2 for i.MXRT1060. The revision history included in the updated documents provides a detailed description of the changes. Changes are summarized below.

For RT1060 Chip Errata:

Added following errata:

* ERR050235 CCM: Incorrect clock setting for CAN affects UART clock gating

For RT1060 Consumer DS, Data Sheet Changes:

1. Updated the SPI NAND Flash in the Section 1.1, Features
2. Updated the features of RT1062 in the Table 1, Ordering information
3. Updated the Table 81, Boot through UART1 and removed the Table, Boot through UART2
4. Updated the figure and table numbers in the Section 6.2, 12 x 12 mm package information
5. Updated the Figure 53, "10 x 10 mm BGA, case x package top, bottom, and side Views" and Figure 54, "12 x 12 mm BGA, case x package top, bottom, and side Views"

For RT1060 Industrial DS, Data Sheet Changes:

1. Updated the SPI NAND Flash in the Section 1.1, Features
2. Updated the Table 81, Boot through UART1 and removed the Table, Boot through UART2
3. Updated the figure and table numbers in the Section 6.2, 12 x 12 mm package information
4. Updated the Figure 53, "10 x 10 mm BGA, case x package top, bottom, and side Views" and Figure 54, "12 x 12 mm BGA, case x package top, bottom, and side Views"

The i.MXRT1060 errata revision 1.1 is attached to this notice, and can be found at:

https://www.nxp.com/products/processors-and-microcontrollers/arm-microcontrollers/i.mx-rt-series/i.mx-rt1060-crossover-processor-with-arm-cortex-m7-core:i.MX-RT1060?tab=Documentation_Tab&linkline=Errata

The i.MXRT1060 data sheet revision 0.2 is attached to this notice, and can be found at:

https://www.nxp.com/products/processors-and-microcontrollers/arm-microcontrollers/i.mx-rt-series/i.mx-rt1060-crossover-processor-with-arm-cortex-m7-core:i.MX-RT1060?tab=Documentation_Tab&linkline=Data-Sheet

Reason

The errata was added for additional technical clarification on some device features.

The data sheets have been updated to correct errors and / or provide additional technical clarification on some device features.

Identification of Affected Products

Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Data Sheet Revision

A new datasheet will be issued

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[View Notification](#)

[Subscription](#)

[Support](#)

[NXP](#) | [Privacy Policy](#) | [Terms of Use](#)

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

Affected Part Numbers

MIMXRT1062CVL5A

MIMXRT1062DVL6A

MIMXRT1061CVJ5A

MIMXRT106LDVL6A

MIMXRT1062DVJ6A

MIMXRT106ADVL6A

MIMXRT106FDVL6A

MIMXRT1062CVJ5A