

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000942I

DATE: 26-May-2018

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------|-------------------|------------------------|-----------------|--------------------|--|
| Reactivation | MAX5116EEE+T | N/A | | | Part reactivated from prior notice: M000918I |
| Discontinuance | DG506C/W+ | N/A | 26-May-2018 | 26-May-2018 | Part is leaded. Request information on lead-free version |
| Discontinuance | DS1809U-050+T&R | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | DS3904U-010+T&R | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | ICL7642C/D-318 | ICL7642BCWE+ | 26-May-2018 | 26-May-2018 | Leaded with a Lead-Free or RoHS Replacement |
| Discontinuance | ICL7642EC/D | ICL7642BCWE+ | 26-May-2018 | 26-May-2018 | Leaded with a Lead-Free or RoHS Replacement |
| Discontinuance | MAX11164EVC+ | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11164EVC+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11165EVC+ | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11165EVC+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11166EVC+ | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11166EVC+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11167EVC+ | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX11167EVC+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX13053AASA+ | MAX13053AEASA+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX13053AASA+T | MAX13053AEASA+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX13054AASA+ | MAX13054AEASA+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX13054AASA+T | MAX13054AEASA+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX15026BETD/V+ | MAX15026BETD+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX15026BETD/V+T | MAX15026BETD+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX15106GWP+ | MAX15106BGWP+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX15106GWP+T | MAX15106BGWP+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX1533AETJ+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX1558ETB+TG29 | MAX1558ETB+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517B+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517B+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |

| Discontinuance | MAX16517D+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
|----------------|------------------|---------------|-------------|-------------|--|
| | | N/A | | | · |
| Discontinuance | MAX16517D+T | | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517F+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517F+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517G+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517G+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517H+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX16517H+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX1711C/D | N/A | 26-May-2018 | 26-May-2018 | Part is leaded. Request information on lead-free version |
| Discontinuance | MAX176EVKIT-DIP | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX1819EBL18+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX183ACNG+W | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX197EVKIT-DIP | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX20732EPL+ | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX20732EPL+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX20732EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX20736EPL+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX20740EPL+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX20740EPL+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX20740EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX20751EVKIT3# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX20771EPS+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX20771EPS+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX2119CTI+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX274AENG+W | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX2982GCD+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX3001EEWP+TW | MAX3001EEUP+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3221CAE+G1Z | MAX3221CAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3221EAE+G1Z | MAX3221EAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3221EEAE+G1Z | MAX3221EEAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3222CAP+G1Z | MAX3222CAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3222ECAP+G1Z | MAX3222ECAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3222ECAP+TG1Z | MAX3222ECAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3223EAP+TG1Z | MAX3223EAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3223ECAP+G1Z | MAX3223ECAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3223ECAP+TG1Z | MAX3223ECAP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |

| Discontinuance | MAX3223EUP+TG1Z | MAX3223EUP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
|----------------|-------------------|---------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX3225EEUP+G1Z | MAX3225EEUP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3225EEUP+TG1Z | MAX3225EEUP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3226EAE+G1Z | MAX3226EAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3226EAE+TG1Z | MAX3226EAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3227EEAE+G1Z | MAX3227EEAE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232CS+G1Z | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232CSE+G1Z | MAX3232CSE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232CWE+G1Z | MAX3232CWE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232CWE+TG1Z | MAX3232CWE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232ECWE+TG074 | MAX3232ECWE+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232EEUP+G1Z | MAX3232EEUP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232EEUP+TG1Z | MAX3232EEUP+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232EEWE+G1Z | MAX3232EEWE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232EEWE+TG035 | MAX3232EEWE+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232EEWE+TG1Z | MAX3232EEWE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232ESE+G1Z | MAX3232ESE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3232ESE+TG1Z | MAX3232ESE+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241CAI+G1Z | MAX3241CAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241CAI+TG1Z | MAX3241CAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECAI+G1Z | MAX3241ECAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECAI+TG1Z | MAX3241ECAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECUI+G1Z | MAX3241ECUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECUI+TG1Z | MAX3241ECUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECWI+G1Z | MAX3241ECWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241ECWI+TG1Z | MAX3241ECWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EEAI+G1Z | MAX3241EEAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EEAI+TG1Z | MAX3241EEAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EEUI+G1Z | MAX3241EEUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EEUI+TG1Z | MAX3241EEUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EWI+G1Z | MAX3241EWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3241EWI+TG1Z | MAX3241EWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243CAI+G1Z | MAX3243CAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243CUI+G1Z | MAX3243CUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243CUI+TG1Z | MAX3243CUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243EAI+G1Z | MAX3243EAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |

| Discontinuance | MAX3243EAI+TG1Z | MAX3243EAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
|----------------|--------------------|----------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX3243ECAI+G1Z | MAX3243ECAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243ECAI+TG1Z | MAX3243ECAI+ | | | • |
| | MAX3243ECUI+G1Z | MAX3243ECUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | | | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243ECUI+TG1Z | MAX3243ECUI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243EEAL+G1Z | MAX3243EEAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3243EEAI+TG1Z | MAX3243EEAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3244ECWI+G1Z | MAX3244ECWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3244ECWI+TG1Z | MAX3244ECWI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3245CAI+G1Z | MAX3245CAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3245CAI+TG1Z | MAX3245CAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3245ECAI+G1Z | MAX3245ECAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3245ECAI+TG1Z | MAX3245ECAI+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX33053ASA+ | MAX33053EASA+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX33053ASA+T | MAX33053EASA+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX33054ASA+ | MAX33054EASA+ | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX33054ASA+T | MAX33054EASA+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX3384ECAP+ | MAX3384ECWN+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3384ECAP+T | MAX3384ECWN+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3384EEAP+ | MAX3384ECWN+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3384EEAP+T | MAX3384ECWN+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX4236EUT+TG29 | MAX4236EUT+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX4420EEE+T | MAX4420ESA+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX4478AUD/V+CQS | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX4478AUD/V+TCQS | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX4492AUD+TG29 | MAX4492AUD+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX5026EUT+TG52 | MAX5026EUT+T | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX5120AEE+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX514BCWI+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX5732AUTN+G116 | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX6380XR41+G125 | MAX6380XR41+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX6640EVKIT | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | MAX6759UTZD3/V+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX6759UTZD3/V+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX6769AGALD2/VS+ | N/A | 26-May-2018 | 26-May-2018 | The part was not released |
| Discontinuance | MAX6769AGALD2/VS+T | N/A | 26-May-2018 | 26-May-2018 | The part was not released |

| Discontinuance | MAX7645ACPP+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
|----------------|--------------------|-----------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX7645BCPP+T | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8630WETD20+G29 | MAX8630WETD20+ | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8630WETD20+TG29 | MAX8630WETD20+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9714ETJ+TG29 | MAX9714ETJ+T | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | MX7545LN+4 | N/A | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | VT1527SV2EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT1527SV3EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT1577SV2EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT1596MFQR | VT1596MFQX | 26-May-2018 | 26-May-2018 | Part can no longer be manufactured |
| Discontinuance | VT273S2EVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT5051PEVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT5052PEVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| Discontinuance | VT7505CEVKIT# | N/A | 26-May-2018 | 26-May-2018 | EVKIT is No Longer Supported |
| | | | | | |