

PCN Number:	20150305000	PCN Date:	03/09/2015
Title:	Datasheet update for TPS53318/TPS53319		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
☐ Assembly Site	☐ Design	☐ Wafer Bump Site	
☐ Assembly Process	☒ Data Sheet	☐ Wafer Bump Material	
☐ Assembly Materials	☐ Part number change	☐ Wafer Bump Process	
☐ Mechanical Specification	☐ Test Site	☐ Wafer Fab Site	
☐ Packing/Shipping/Labeling	☐ Test Process	☐ Wafer Fab Materials	
		☐ Wafer Fab Process	

PCN Details								
Description of Change:								
Texas Instruments Incorporated is announcing an information-only product change notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details:								
								
TPS53318, TPS53319 SLUSAY8D – JUNE 2012 – REVISED FEBRUARY 2015 www.ti.com								
Changes from Revision C (December 2014) to Revision D		Page						
- Added recommendation for ROVP connection when ROVP function is not needed in <i>Pin Functions</i> table - Corrected typographical error. Changed "when the VDD voltage rises above 1 V" to "when the VDD voltage rises above 2 V" in the <i>5-V LDO and VREG Start-Up</i> section. - Added <i>ROVP Pin Design Note</i> in <i>Redundant Overvoltage Protection (OVP)</i> section		3 14 17						
The datasheet number will be changing. <table border="1" style="width: 100%;"> <tr> <td>Device Family</td> <td>Change From:</td> <td>Change To:</td> </tr> <tr> <td>TPS53318/TPS53319</td> <td>SLUSAY8C</td> <td>SLUSAY8D</td> </tr> </table>			Device Family	Change From:	Change To:	TPS53318/TPS53319	SLUSAY8C	SLUSAY8D
Device Family	Change From:	Change To:						
TPS53318/TPS53319	SLUSAY8C	SLUSAY8D						
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/tps53318								
Reason for Change:								
To more accurately reflect device characteristics.								
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):								
Electrical specification performance changes as indicated above.								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								
TPS53318DQPR	TPS53318DQPT	TPS53319DQPR						
		TPS53319DQPT						

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com