Product Change Notification - SYST-06CYNQ076

Date: 07 Jul 2017

Product Category: USB to Ethernet Controllers

Affected CPNs:

Notification subject: Data Sheet - LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC Data Sheet Document Revision

Notification text: SYST-06CYNQ076

Microchip has released a new DeviceDoc for the LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC of devices. If you are using one of these devices please read the document located at LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC.

Notification Status: Final

Description of Change:
1) Removed +2.5V from Switcher Input Voltage description for Table 3-2, "Pin Assignments".
2) For Figure 4-1, "Power Connection Diagram", Changed +2.5-3.3V to +3.3V and Modified note under figure

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 07 July 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN7850T-I/8JX
LAN7850T/8JX
LAN7850-I/8JX
LAN7850/8JX