
This document was generated on 08/22/2016

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**

**Part Number:** 0732510033
**Status:** Active
**Overview:** SMA RF Connectors
**Description:** 50 Ohms, SMA Plug, Solder, RG-402 (.141) Cable, Stainless Steel Body with 0.76µm Gold Plating, 0.76µm Gold Plating on Contact, Bag



*Series image - Reference only*

**Documents:**
Drawing (PDF)
RoHS Certificate of Compliance (PDF)

| | |
|---|---|
| **General** | |
| Product Family | RF/Coax Connectors |
| Series | 73251 |
| Overview | SMA RF Connectors |
| Product Name | SMA |
| Style | Cable |
| UPC | 887191245942 |
| Wire/Cable Type | RG-402 3.58mm |
| **Physical** | |
| Gender | Plug |
| Keying to Mating Part | None |
| Net Weight | 2.193/g |
| Orientation | Straight |
| PCB Mounting | N/A |
| Packaging Type | Bag |
| Panel Mount | No |
| Panel Mount Method | N/A |
| Reverse Polar | No |
| **Electrical** | |
| Impedance | 50# |
| **Solder Process Data** | |
| Lead-freeProcess Capability | N/A |
| **Material Info** | |
| **Reference - Drawing Numbers** | |
| Sales Drawing | SD-73251-003 |

**EU ELV**
**Not Relevant**

**EU RoHS**
**Compliant with Exemption 6(c)**

**China RoHS**

**REACH SVHC**
Contained Per - ED/21/2016 (20 June 2016)
2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)p

**Halogen-Free Status**
**Low-Halogen**

**Need more information on product environmental compliance?**

Email productcompliance@molex.com
Please visit the Contact Us section for any non-product compliance questions.

| | |
|---|---|
| China ROHS | 50 Image |
| ELV | Not Relevant |

**Search Parts in this Series**
73251 Series

This document was generated on 08/22/2016

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**