

## M28320

### Errata

**Literature Affected:** 12-Port DS3/E3/STS-1 Digital Jitter Attenuator (DJAT) and STS-1 to DS3/E3 Desynchronizer Data Sheet (document #500119d)

On page 5-14:

Section 5.1.3.20: 0x1F0 should be 0xF0

On page 5-15:

Section 5.1.3.21: 0x1F1 should be 0xF1

Section 5.1.3.22: 0x1F2 should be 0x0F2

Section 5.1.3.23: 0x1F3 should be 0x0F3

Section 5.1.3.24: 0x1F4 should be 0x0F4

Section 5.1.3.25: 0x1F5 should be 0x0F5