



Test Procedure for the NCP382LMN15AGEVB Evaluation Board

Equipment Needed:

1. Power Supply (5V, 3A)
2. Potentiometer/Load (100 Ω , 10W)
3. Multimeter

Note: Cables should be as short as possible to lower their inductance value – otherwise you may harm either the input or output pins of the device

Set-up & Test:

1. Apply $V_{in} = 4V$ dc (Over Current Limit = 1.5A) on IN test point.
2. Connect a 100 Ω , 10W load between Output1 test point and GND strap.
1. Toggle EN1 strap between Low and High sides.
2. Output1 must change from 0 to 4V by toggling the EN1 switch.
3. Disconnect load from Output1 and connect it to Output2 test point.
4. Toggle EN2 strap between Low and High sides.
5. Output2 must change from 0 to 4V by toggling the EN2 switch.