

PCN-CCX-001105

Product Change Notice

Issue Date: October 2, 2018

<u>Change Type:</u> New factory site code

Parts Affected:

OCE14102B-UT OCE14102B-UX OCE14104B-UX OCE14102B-UM

Description and Extent of Change:

An additional manufacturing site at Flex Penang in Malaysia will be brought online. The same manufacturing processes at the current Flex Zhuhai site will apply. To ensure product quality is equivalent to the current manufactured products, a transition build will be scheduled, evaluated, and first article inspections completed prior to approval for shipment from the additional facility.

Reasons for Change:

Additional capacity for continuity of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:

Product shipments using this change will begin in or after October 2018. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

Qualification Data:

Electronic First Article reports (FAIs) will be available on request.

Software / Firmware Update:

None

Recommended Action to be Taken by Customer:

Customer acknowledgement of this PCN and provide a new factory site code (if applicable) for CCX OneConnect products produced at Flex Penang by October 5th, 2018.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.