



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000810

DATE: 11-Sep-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX16501M1EVKIT#	N/A			Reactivation
Reactivation	MAX16501V1EVKIT#	N/A			Reactivation
Reactivation	MAX16520M1EVKIT#	N/A			Part reactivated from prior notice: M000860I
Discontinuance	80515-FPBM-TFP2	80515-FPBM-TFP3	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	DS1981U-F3-114C	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	DS2401X-88A-C2+1T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	DS2401X-88B-82+1T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	DSECASH	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAX14636EVKIT#	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAX15153EVKIT#	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAX17129ETE+	N/A	12-Mar-2016	10-Sep-2017	Part can be not longer manufactured
Discontinuance	MAX17129ETE+T	N/A	12-Mar-2016	10-Sep-2017	Part can be not longer manufactured
Discontinuance	MAX17129EVKIT+	N/A	12-Mar-2016	10-Sep-2017	Part can be not longer manufactured
Discontinuance	MAX17149ETE+	N/A	12-Mar-2016	10-Sep-2017	Part can be not longer manufactured
Discontinuance	MAX17149ETE+T	N/A	12-Mar-2016	10-Sep-2017	Part can be not longer manufactured
Discontinuance	MAX17845ACB/V+	N/A	11-Sep-2015	11-Sep-2015	The part was not released
Discontinuance	MAX2143BEGH/V+TCKK	MAX2143DEGH/V+CCK	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MAX4026EUP+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MAX4026EUP+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MAX4026EWP+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MAX66901-K00#	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAX66903-K00	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAX88100EDT+	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88100EDT+T	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88120EFD+	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88120EFD+T	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 12-Oct-2015

Discontinuance	MAX88120EVSYS#	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88200EFD+	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88200EFD+T	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88200EVSYS#	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88920EFD+	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88920EFD+T	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88920EVSYS#	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88922AEFD+	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88922AEFD+T	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX88922EVSYS#	N/A	11-Sep-2015	11-Sep-2015	Part can be not longer manufactured
Discontinuance	MAX9663EFR+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MAXM17505DEMBD#	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MAXQ626EVKIT#	N/A	11-Sep-2015	11-Sep-2015	EVKIT is No Longer Supported
Discontinuance	MXB7843EEE+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7843EEE+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7843EUE+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7843EUE+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7846EEE+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7846EEE+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7846EUE+	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7846EUE+T	N/A	14-Mar-2016	14-Mar-2016	Part can no longer be manufactured
Discontinuance	MXB7846EVC16	N/A	11-Sep-2015	11-Sep-2015	Part can no longer be manufactured
Discontinuance	MXB7846EVKIT	N/A	11-Sep-2015	11-Sep-2015	Part can no longer be manufactured