

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000838I

DATE: 26-Feb-2015

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------------|--------------------|------------------------|-----------------|--------------------|--|
| Lead-Free Conversion | DS1982A1-008-A0#F3 | DS1982A1-008-A0+F3 | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | DS1990A-035-01#F5C | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | DS5250F-825 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX133CQH-C10219 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6353MSUK | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6353MSUK-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6353MTUK | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6353MTUK-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6649MUA-G002 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6806UR23 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6806UR23-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6806UR46 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX6806UR46-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX845EUA-C74402 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MX7528KEQP-C40203 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part is leaded. Request information on lead-free version |
| Discontinuance | 5962-8770202RA | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 5962-8961603VA | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 71M6403-IGTR/F | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 73S8014BL-IL/F | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 73S8014BL-ILR/F | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 73S8014BN-IL/F | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 73S8014BN-ILR/F | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 78M6631-IM/F/P48 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 78M6631-IMR/F/P48 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0080-21 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0441-20+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuones | 806-0468-84 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | | N/A | | | The part was not released |
| Discontinuance | 806-0486-90-A4 | | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0498-20-A4 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0507-31+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0507-31+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0541-04-A9 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | 806-0604-01 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | 806-0616-23+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0616-23+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0657-25+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-0657-25+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | 806-MP22-2E+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | ADC0820BCJ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | ADC0820BJ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | ADC0820CCJ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | ADC0820CJ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | DG212ETE+C4J | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DG425C/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1100U-200+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1643P-85+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1743-70+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1743P-85IND+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1782G+T&R | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1782W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1834X/T&R | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1990A-037-01+F3 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS1990A-037-01+F5 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS26518GA2+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS26518GNA2+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS3508E+T&R | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS3508E+T&R/C | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS4302Z-020+T&R | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DS5230F-825+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | DSK1G+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | ICL7135CJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | ICL7632BCPE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| D: // | MAYAGODOFF T | N1/A | 00 5 1 0045 | 05 5 1 0047 | - 1 |
|----------------|----------------|------|-------------|-------------|------------------------------------|
| Discontinuance | MAX1026BCEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1038MEEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1103EUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1103EUA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX11046ECB+TW | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX11215EUG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1136KEUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1136LEUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX113MRG | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1156AEUP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1156AEUP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1156BEUP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1156BEUP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX117MJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX11871AEET+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX11871AEET+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX11874EWJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX11874EWJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX118C/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX118MJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1202BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1203AMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1204BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1236MEUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1303AEUP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX13047EETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX13047EETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1421CCM+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1421CCM+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14511EEVB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14522EZC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX14522EZC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX14539EEVB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14612ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14612ETE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX14675ESE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX146BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
|----------------|------------------|---------------|-------------|-------------|---|
| Discontinuance | MAX14825ETG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14825ETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14901EAGM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14901EAGM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14962ETN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX14962ETN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15025DATB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15025DATB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15069ETN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15069ETN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX150AMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX150BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX15100EWL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15100EWL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1513AETP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1513AETP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1517AETJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1518AETJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX152MJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1535BETJ+ | MAX8731AETI+T | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1535BETJ+T | MAX8731AETI+T | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1535DETJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1537AETX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX153MJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX15425GTL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX15425GTL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1542ETP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1542ETP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1576YETG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX158AEJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX158AMJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX158BEJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX158BMJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1601EAI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Web Clean-up: Part is obsolete & not currently released for s |
| Discontinuance | MAX16098XS16OMA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX16098XS16OMA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX16098XS29OMB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16098XS29OMB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS16HAC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS16HAC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS26OMA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS26OMA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS29BMA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS29BMA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS46VGB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX16099XS46VGB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX160MJN | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX160MJN/HR | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX161AMJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX161CMJI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX17004AETJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17007ETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17007ETI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17007GTI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX17007GTI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17008GTI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17011GTL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1707ETG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1707ETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17085GTL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17109ETJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1710EEG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1710EEG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1712EEG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1712EEG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1717BEEG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1717BEEG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17400ETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17508ATJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17508ATJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17711GTM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| D ' ' | 141/4777FF1 | 21/2 | 00 5 1 0045 | 05 5 1 0047 | - |
|----------------|------------------|------|-------------|-------------|------------------------------------|
| Discontinuance | MAX1777EEI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1777EEI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX17911GTL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1801EKA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1801EKA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1804EUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1804EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1820XEBC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1820YEBC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1820YEBC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1827ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1827ETL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1855EEG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1855EEG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX186CMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1883EUP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX188BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX188DMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX192BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX19695EXF+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1977AEEI | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX1994ETM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX1994ETM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2022ETX+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2022ETX+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2104CCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2212ETA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2242EBC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2242EBC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2242EBC+TWG50 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2242EBC+WG50 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX252ACHL | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX252AEHL | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX252BCHL | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX252BCHL-WG002 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX252BEHL | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |

| Discontinuance | MAX252BEHL-W | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
|----------------|----------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX2552ETN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2631EUK+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2631EUK+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX266ACPI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX2901EGI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3202EEBS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3202EEBS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3228EBV+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3228EBV+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3246ECBX-T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3288CUE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3344EEBE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3344EEBE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3353EEBP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3353EEBP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3408EUK+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3455EETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3507ETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3524EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3635N+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3755CCM+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3774CEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3774CEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX3878E/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4286ESA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4286ESA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4356ECD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4357ECD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4357ECD+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4397DACTM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX4397DACTM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4397SACTM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX4397SACTM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4415EUA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX44255AUE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX4433EUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|--------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX4433EUA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4453EZA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4653CSE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4696EBT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4696EBT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4698EBT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4717EBC+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4746HELB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4746HELB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4747EBE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4747EBE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4748EBE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4748EBE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4748ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4748ETE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4750EBE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4750EBE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4756AETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4756ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4758EBX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4758EBX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4759ETX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4759ETX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760AEBX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760AEBX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760AETX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760AEWX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760EBX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760EBX+TW | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4760EBX+W | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4761EBX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4832ETT33C+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4832ETT33C+G19 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4832ETT33C+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4832ETT33C+TG19 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX4844ELT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-----------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX4844ELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4850ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4850ETE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4850HETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4851ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4851HETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4853ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4853HETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4864ELT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4864ELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4866ELT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4866ELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4866EUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4867ELT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4867ELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4881ETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4893BETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4893BETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4913AELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4913BELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4914AELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4914AEUK+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4916AELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4916BELT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4919BETD+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4919BETD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4920BETD+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4920BETD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4940BETN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4940BETN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4943ELA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944BELA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944BELA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+G47 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+G50 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX4944LELA+G65 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX4944LELA+GC7 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+TG47 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+TG50 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+TG65 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4944LELA+TGC7 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4945BELA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4945BELA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4957EBC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4957EBC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4957ETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4957ETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4958EBC+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4958EBC+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4958ETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4958ETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4960ELB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4960ELB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4960EUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4960EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4991EVB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX4991EVB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5037ETH+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5038EAI33+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5038EAI33+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5041AEAI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5059AUI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5059AUI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5059EUI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5059EUI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5065EAI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5065EAI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5067ETH+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5067ETH+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5068DAUE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX5068DAUE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX5068EAUE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5068EAUE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX506AMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX506BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX508BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5095CAUA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5095CAUA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX509AMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX509BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5165MCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165MCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165MECM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165MECM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165NCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165NCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165NECM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5165NECM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5166MCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5166MCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5166MECM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5166MECM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5167LCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5167LCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5167NCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5167NCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168LCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168LCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168MCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168MCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168NCCM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5168NCCM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX521BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5250BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5251BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX525AMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |

| Discontinuance | MAX528MJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
|----------------|------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX5360PEUK+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5360PEUK+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5380PEUK+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5380PEUK+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5418NETA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5418NETA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5434PEZT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5434PEZT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5435NEZT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5435NEZT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5435PEZT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5435PEZT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5490SC04000+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RA01100+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RA01100+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RB01100+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RB01100+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RC01100+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5492RC01100+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5762BUCB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5881ACXW+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5881ACXW+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5900LAETT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5900LAETT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5900LAEUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5900LAEUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX5901LBETT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LBETT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LBEUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LBEUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LCETT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LCETT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LCEUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5901LCEUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5902LBETT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX5902LBETT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX5902LBEUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5902LBEUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5907EEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5907UEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5907UEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5913EMH+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5913EMH+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5913EMH+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5913EMH+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5914EMH+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5914EMH+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5914EMH+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5914EMH+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5918AEEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5918AEEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5918LEEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5918LEEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5919AEEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5919AEEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5919LEEE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5919LEEE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5992AETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5992BETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5992CETG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX5992CETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX615C/D-C70405 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX615C/D-C70816 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US-C74423 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX6315US28D1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US28D1+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US28D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US28D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US28D4+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US28D4+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US32D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6315US32D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-----------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6315US35D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US35D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US40D1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US40D1+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US43D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US43D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US46D1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US46D1+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US47D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US47D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US47D4+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US47D4+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US48D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US48D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US49D3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6315US49D3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6338EUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6338EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6338FUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6338FUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339EUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339EUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339FUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339FUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339GUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339GUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339HUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6339HUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6344RUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6344RUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6344TUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6344TUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6345MUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6345MUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6345RUT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6345RUT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|----------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX6353MRUK-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX6353TYUK-T | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX6364HUT23+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6364HUT23+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6364HUT46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6364HUT46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS33+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS33+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS34+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS34+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS35+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS35+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS36+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS36+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS37+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS37+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS38+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS38+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS39+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS39+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS40+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS40+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS41+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS41+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS42+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS42+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS43+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS43+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS44+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS44+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS45+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS45+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6403BS46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS33+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6404BS33+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6404BS34+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS34+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS35+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS35+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS36+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS36+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS37+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS37+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS38+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS38+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS39+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS39+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS40+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS40+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS41+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS41+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS42+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS42+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS43+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS43+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS44+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS44+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS45+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS45+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6404BS46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS30+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS30+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS33+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS33+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS34+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6406BS34+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6407BS33+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6407BS33+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6407BS34+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6407BS34+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX6409BS44+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6409BS44+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS42+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS42+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS43+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS43+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS45+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6410BS45+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS35+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS35+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS36+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS36+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS37+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS37+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS38+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS38+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS39+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS39+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS40+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS40+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS41+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS41+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS42+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS42+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS43+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6411BS43+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423US17 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX6423US17+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423US17+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423XS17 | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX6423XS17+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423XS17+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423XS44+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6423XS44+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6429AGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6429AHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429AJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429BJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429CJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429DJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| 5 1 | | | | | |
|----------------|---------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6429EIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429EJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FGUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FGUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FHUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FHUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FIUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FIUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FJUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429FJUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KRUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KRUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429KTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LRUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LRUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429LTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MRUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MRUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429MTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6429NQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6429NRUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NRUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429NTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429ORUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429ORUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429OTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PQUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PQUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PRUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PRUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PSUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PSUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PTUR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6429PTUR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432AJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| 5 | | **** | | | |
|----------------|---------------|------|-------------|-------------|---------------------------|
| Discontinuance | MAX6432BIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432BJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432CJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432DJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432EJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FGUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FGUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FHUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FHUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FIUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FIUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FJUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432FJUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6432KQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|---------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6432KRUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KRUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432KTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LRUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LRUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432LTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MRUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MRUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432MTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NRUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NRUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432NTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432OQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432OQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432ORUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432ORUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432OSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6432OSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6432OTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432OTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PQUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PQUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PRUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PRUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PSUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PSUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PTUS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6432PTUS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6438UT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6438UT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6439UTKQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6439UTKQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAAGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAAGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| 5 1 | | | | | |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAAIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAAJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAAJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAAJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KABGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KABGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KABHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KABHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KABJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KABJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KABJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KACGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KACGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KACHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KACHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KACJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KACJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KACJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KADGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KADGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KADHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KADHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KADIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KADIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KADJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAEGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAEGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAEHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAEHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAEIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAEIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAEJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAFGRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAFGRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFGZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAFHTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAFHTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFHZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFISD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFISD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFISD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFISD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFITD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFITD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFITD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFITD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAFIWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAFIWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFIZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| | | | | | <u> </u> |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAFJZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAFJZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAKRSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAKRSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKRZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAKSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAKSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAKTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAKTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAKTZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KALRRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KALRRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALRZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KALSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KALSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KALTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KALTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KALTZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAMQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAMQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMRZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAMSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAMSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAMTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAMTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAMTZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KANQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KANQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANRZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KANSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KANSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KANTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|----------------------------|----------------------------|---------------------------|
| Discontinuance | MAX6442KANTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| | MAX6442KANTZD3+T | N/A | | | |
| Discontinuance | | N/A | 26-Feb-2015 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTZD7+ | N/A | | 25-Feb-2017 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KANTZD7+T | | 26-Feb-2015 | | The part was not released |
| Discontinuance | MAX6442KAOQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAOQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAOQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAORZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAORZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAORZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAOTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAOTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAOTZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAPQVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAPQVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPQZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAPRYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAPRYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPRZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPSZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6442KAPTRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6442KAPTRD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTRD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTSD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTSD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTSD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTSD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTTD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTTD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTTD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTTD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6442KAPTZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6481BL25BD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6481BL25BD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX650BC/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6514UKN035+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6514UKN035+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6514UKP075+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6514UKP075+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6515UKN035+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6515UKN035+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6515UKP075+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-----------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6515UKP075+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6518UKN035+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6518UKN035+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6518UKP075+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6518UKP075+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6519UKN035+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6519UKN035+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6712ZEXS+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6712ZEXS+10 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6712ZEXS+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6712ZEXS+T10 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TALAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TALAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TALTD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TALTD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TARAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TARAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TATWD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TATWD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TATZD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TATZD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAWAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAWAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAWED0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAWED0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAZAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAZAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAZWD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6760TAZWD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TALAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TALAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TALTD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TALTD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TARAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TARAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6761TATAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-----------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6761TATAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TATWD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TATWD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TATZD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TATZD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAWAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAWAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAWED0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAWED0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAZAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAZAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAZWD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6761TAZWD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALRD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALRD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALTD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TALTD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TARAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TARAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAWAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAWAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAWED0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAWED0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAZAD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAZAD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAZWD0+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6762TAZWD0+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806UR23+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806UR23+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806UR46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806UR46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806US23+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806US23+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6806US46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|----------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX6806US46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806XR23+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806XR23+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806XR46+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6806XR46+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6840XSD1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6840XSD1+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6840XSD4+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6840XSD4+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KARD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KARD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KARD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KARD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KASD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KASD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KASD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KASD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KATD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KATD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KATD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KATD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAVD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAVD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAVD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAVD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAWD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAWD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAWD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAWD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAYD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAYD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAYD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAYD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAZD3+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6849KAZD3+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX6849KAZD7+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|----------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX6849KAZD7+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6933AAX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX6981AUE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7231AFC/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7231AFI/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7360EWX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7440ESD+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7440ESD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7441ESD+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7441ESD+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX7645AEJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX7645BEJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX7645BMJP | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX77235EWW+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX77660ZEWV+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX77677EWW+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX77677EWW+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX810ZEXR+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX810ZEXR+10 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX810ZEXR+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX810ZEXR+T10 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8507ETE+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8507ETE+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8524EEI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8524EEI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8525EEI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8525EEI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8530EWTB2+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8530EWTB2+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8539EEI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8539EEI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8555ETB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8555ETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8555EUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8555EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX8594AETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX8621ETG+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8621YETG+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8658ETN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8659ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8671AETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8671AETL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8698ERO+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8698ERO+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8704EUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8705ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8705ETL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8707ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8707ETL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8709BETI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8736AGTL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MAX8736AGTL+C3X | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8736AGTL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8736AGTL+TG24 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8757ETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8757ETI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8767ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8773GTL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8795BETJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8804VETA+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8804VETA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX88260EDT+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX88260EDT+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8826ETL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8829EWV+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8829EWV+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8894EWZ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8894EWZ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8907AEWN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8907AEWN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8907BEWN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |

| Discontinuance | MAX8907BEWN+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|------------------|-----|-------------|-------------|---------------------------|
| Discontinuance | MAX8966EWW+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8966EWW+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8995XEWA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX8995YEWA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9222EUM+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9222EUM+D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9222EUM+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9222EUM+TD | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9223ETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9223ETI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9317BECJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9317BECJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9317ECJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9317ECJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9326EQI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9326EQI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9423EHJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9423EHJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9427EHJ+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9427EHJ+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9625AKA+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9688RETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9688RETI+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9702BETI+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEBL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEBL+G45 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEBL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEBL+TG45 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CETB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEUB+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9718CEUB+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9775EBX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9775EBX+GA6 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9775EBX+GD7 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| | | | | | |

| Discontinuance | MAX9775EBX+TGA6 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
|----------------|-----------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MAX9796EBX+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9796EBX+GA6 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9796EBX+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9796EBX+TG45 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9796EBX+TGA6 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9840AEWL+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX9840AEWL+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX98711EVKIT# | N/A | 26-Feb-2015 | 25-Feb-2017 | EVKIT is No Longer Supported |
| Discontinuance | MAX98711EWV+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MAX98711EWV+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7224BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7224CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7224KP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7225BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7225CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7225UQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7248AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7248JP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7248SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7521JQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7521SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7521TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7524J/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7528AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7528BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7528CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7528SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7528TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7534AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7534BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7534TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7536JN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7536TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7537J/D | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7541AAQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |

| Discontinuance | MX7541AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
|----------------|--------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MX7541ASQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7541ATQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7541SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7541TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545ABQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545ACQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545AUQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545GCQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545GUQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7545SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7548AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7549AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7549BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7549JCWP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JCWP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JEWP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JEWP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549JP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KCWP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KCWP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KEWP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KEWP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KN+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549KP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7549SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7549TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7574AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7574BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7574SQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |

| Discontinuance | MX7574TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
|----------------|-------------------|-----|-------------|-------------|------------------------------------|
| Discontinuance | MX7575AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7575KP+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7575KP+T | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | MX7576AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7581AQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7581BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7581CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7581UQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7582BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7628BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7820BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7821BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7821TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7828BQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7828CQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7828TQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MX7828UQ | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | MXL1028C/D | N/A | 26-Feb-2015 | 25-Feb-2017 | Part can no longer be manufactured |
| Discontinuance | PE04Z | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | PE09Z | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | PM35Y | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | SDDSP1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | SDESP1+ | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |
| Discontinuance | ZLP323H2016GR55K4 | N/A | 26-Feb-2015 | 25-Feb-2017 | The part was not released |