

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000874A

DATE: 08-Oct-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX3243EEAI+C9V	MAX3243EEAI+	19-Mar-2019	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526CCWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526CCWG+T	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526CEWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526DCWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526DCWG+T	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX526DEWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX527CCWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX527CEWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX527DCWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX527DCWG+T	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured
Change to Prior Notice	MAX527DEWG+	N/A	15-Dec-2018	12-Mar-2020	Part can no longer be manufactured