

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000910I

DATE: 18-Oct-2016

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	73S8014R-IL/F2	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014R-ILR/F2	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014RN-ILR/F1	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014RT-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014RT-IL/F2	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014RT-ILR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	73S8014RT-ILR/F2	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Lead-Free Conversion	STM1E-SFP25	N/A	18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	73S8009R-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8009R-ILR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8010C-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8010C-ILR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8014R-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8014R-ILR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8014RN-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8024C-IL/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	73S8024C-ILR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	78Q8392LA03-28CH/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	78Q8392LA03-CHR/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	78Q8392LA03-CP/F	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	DG442DY	DG442DY+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS1644-120+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2430A-002-E1		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	DSQ09G5-004-740		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MAX11835TEVS+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX11874EVKIT#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported

Discontinuance	MAX13301EVKIT#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX14833ETB+		18-Oct-2016	18-Oct-2016	The part was not released
Discontinuance	MAX15041AETE+	N/A	18-Oct-2016	18-Oct-2016	The part was not released
Discontinuance	MAX16804ATP+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16804ATP+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16805ATP+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16805ATP+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16806ATP+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16806EVCMAXQU+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX16806EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX16806EVMAXQUSB+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX16807AUI+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16807AUI+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16807AUI+TG069	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16807EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX16808AUI+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16808AUI+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16809ATU+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16809ATU+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX16915AUB/V+	N/A	18-Oct-2016	18-Oct-2016	The part was not released
Discontinuance	MAX1719EUT	MAX1719EUT+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1735EUK25	MAX1735EUK25+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1742EEE	MAX1742EEE+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1759EUB	MAX1759EUB+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1773EUP	N/A	18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MAX17824EVMINIQU#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX17841BGUE/V+GC	MAX17841BUE/V+CNY	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX17841BGUE/V+TGC	MAX17841BUE/V+TCNY	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX1840EUB	MAX1840EUB+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1857EUA47	MAX1857EUA47+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1898EUB41	MAX1898EUB41+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX20051ATC/V+		18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX20051AUD/V+G2Z	MAX20051AUD/V+	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX20051AUD/V+G2ZW	MAX20051AUD/V+T	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX20051AUD/V+TG2W	MAX20051AUD/V+T	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX20051AUD/V+TG2Z	MAX20051AUD/V+T	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured

Discontinuance	MAX20080LATM/V+CX	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX20080LATM/V+TCX	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX253CSA		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MAX253CUA		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MAX253CUA-T		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MAX303MSE/PR	MAX303MSE/PR+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3273ETG+	MAX3738ETG+	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX34451ETN+	MAX34451ETNA1+	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX34463EXQA1+	MAX34463EXQA2+	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3747BEUB+CBK	MAX3747BEUB+T	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3747BEUB+TCBK	MAX3747BEUB+T	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3748AEVKIT	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX3784AEVKIT	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX3797E/D+	MAX24005E/D+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX4533EAP	MAX4533EAP+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6616EVCMODU	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX786CAI	MAX786CAI+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX88130EVSYS#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX8875EUK33-T	MAX8875EUK33+T	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX8878EUK25	MAX8878EUK25+	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9209EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM+CB5	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209EUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209GUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209GUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9209GUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9210EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9210EUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9210EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9210EUM+TDS	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9213EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9213EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured

<b>5</b>			40.0 4.0040	12.2 . 22.4	
Discontinuance	MAX9213EUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9213EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9214EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9214EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9234EUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9236EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9236EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9236EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9236EUM-D	MAX9236EUM+D	18-Oct-2016	18-Oct-2016	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX9242EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242EUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242EUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242EUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242GUM+	MAX9242GUM+D	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242GUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242GUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242GUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9242GUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM+TDG002	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244EUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9244GUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246EUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246EUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246EUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246EUM+TDG002	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured

Discontinuance	MAX9246EUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246EUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM+D	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM+TD	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM/V+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9246GUM/V+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9515EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX9540EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX9552EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX9662EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX9663EVKIT+	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX9696EVKIT#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAXMR16DEMO1#	N/A	18-Oct-2016	18-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAXREFDES26#		18-Oct-2016	18-Oct-2016	The eval kit is no longer supported
Discontinuance	MXL1535ECWI		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	MXL1535EEWI		18-Oct-2016	18-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	SD417+	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	SD417+007MF	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured
Discontinuance	SD417+T	N/A	18-Oct-2016	18-Oct-2016	Part can no longer be manufactured