

<b>PCN Number:</b>	20141103001	<b>PCN Date:</b>	11/24/2014
<b>Title:</b>	Datasheet update for LM98725		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Phone:</b>	+1(214) 480-6037
<b>Change Type:</b>	<b>Dept:</b>	Quality Services	
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

### PCN Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is being updated to Add cautionary 50ms wait time note and update Device Information Table, Pin Configuration and Functions; Layout; Device and Documentation Support; Mechanical, Packaging, and Ordering Information

The following change history provides further details



#### LM98725

SNAS474G – APRIL 2009 – REVISED OCTOBER 2014

[www.ti.com](http://www.ti.com)

#### Changes from Revision F (January 2014) to Revision G

Page

- Added, updated, or renamed the following sections: Device Information Table, Pin Configuration and Functions; Layout; Device and Documentation Support; Mechanical, Packaging, and Ordering Information ..... 1
- Added "Note" in [Serial Interface](#) ..... 84

The datasheet number will be changing.

Device Family	Change From:	Change To:
LM98725	SNAS474F	<b>SNAS474G</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LM98725>

#### Reason for Change:

Add missing information about wait time.

Correct register writing information.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

LM98725CCMT/NOPB	LM98725CCMTX/NOPB
------------------	-------------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>