

<b>PCN Number:</b>	20161010002	<b>PCN Date:</b>	October 12, 2016
<b>Title:</b>	Datasheet for TPS3813K33-Q1/TPS3813I50-Q1		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is updated as seen in the change revision history below:



#### TPS3813K33-Q1, TPS3813I50-Q1

SPRS288E – MAY 2008 – REVISED OCTOBER 2016

[www.ti.com](http://www.ti.com)

#### Changes from Revision D (June 2015) to Revision E

Page

- Added + 1 back to the  $t_{window,typ}$  equation in the *Programming Window-Watchdog Using an External Capacitor* section ... 11
- Added the *Receiving Notification of Documentation Updates* section ..... 14

Device Family	Change From:	Change To:
TPS3813K33-Q1/TPS3813I50-Q1	SPRS288D	<b>SPRS288E</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/lit/ds/symlink/tps3813i50-q1.pdf>

#### Reason for Change:

To more accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

TPS3813I50QDBVRQ1	TPS3813K33QDBVRQ1
-------------------	-------------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>