

# Customer Information Sheet

DRAWING No.: Z80-444 SHEET 2 OF 2



IF IN DOUBT - ASK

(C)

NOT TO SCALE

THIRD ANGLE PROJECTION


ALL DIMENSIONS IN mm




PART SECTION X-X



Z80-058 DATAPLATE



DETAIL A  
SCALE 12



## NOTES:

1. INSTRUCTION SHEETS ARE AVAILABLE FOR THIS TOOL. REFER TO INSTRUCTION SHEET IS-01.
2. FOR USE WITH M80-20600XX CRIMP T-CONTACT.

|                |      |          |        |
|----------------|------|----------|--------|
| MSP            | I    | 07.04.17 | -----  |
| NAME           | ISS. | DATE     | C/NOTE |
| APPROVED:      |      | M.PERREN |        |
| CHECKED:       |      | S.FLOWER |        |
| DRAWN:         |      | M.PERREN |        |
| CUSTOMER REF.: |      |          |        |
| ASSEMBLY DRG:  |      |          |        |

# HARWIN

www.harwin.com  
technical@harwin.com

THIS DRAWING AND ANY INFORMATION OR DESCRIPTIVE MATTER SET OUT HEREON ARE CONFIDENTIAL AND COPYRIGHT PROPERTY OF THE HARWIN GROUP AND MUST NOT BE DISCLOSED, LOANED, COPIED OR USED FOR MANUFACTURING, TENDERING OR FOR ANY OTHER PURPOSE WITHOUT THEIR WRITTEN PERMISSION.

## TOLERANCES

X. =  $\pm 1\text{mm}$   
X.X =  $\pm 0.25\text{mm}$   
X.XX =  $\pm 0.10\text{mm}$   
X.XXX =  $\pm 0.01\text{mm}$

ANGLES =  $\pm 5^\circ$   
UNLESS STATED

## MATERIAL:

FINISH: CLEAN

S/AREA: mm<sup>2</sup>

## TITLE:

T-CONTACT CRIMP  
POSITIONER

DRAWING NUMBER:

Z80-444

SHT  
2  
OF  
2