

Product Change Notification Number: F05/2011

Date: 2011-10-26

Title: Multilayers (MLH, MLN, MLP, MLI) manufacturing location and I2NC change

Reason for Change:

- ☐ Production
 ☒ Manufacturing Location
 ☐ Product
 ☐ Quality
 ☐ Packaging
 ☐ Material
 ☐ Other

List of Products Subjected to Change:

12NC	Reference	12NC	Reference
433003067031	MLH0402-4N7-03	433003066811	MLI1206-1R5-10
433003067161	MLH0402-56N-5	433003066821	MLI1206-1R8-10
433003067221	MLH0603-2N7-03	433003066831	MLI1206-2R2-10
433003067261	MLH0603-5N6-5	433003066841	MLI1206-2R7-10
433003067281	MLH0603-8N2-5	433003066851	MLI1206-3R3-10
433003067291	MLH0603-10N-5	433003066861	MLI1206-3R9-10
433003067311	MLH0603-15N-5	433003066871	MLI1206-4R7-10
433003067331	MLH0603-22N-5	433003066881	MLI1206-5R6-10
433003067371	MLH0603-47N-5	433003066891	MLI1206-6R8-10
433003067411	MLH0603-R10-5	433003066901	MLI1206-8R2-10
433003067561	MLH0805-10N-5	433003066911	MLI1206-100-10
433003067581	MLH0805-15N-5	433003066921	MLI1206-120-10
433003067641	MLH0805-47N-5	433003066931	MLI1206-150-10
433003067681	MLH0805-R10-5	433003066941	MLI1206-180-10
434103067031	MLH0402-4N7-03	433003065671	MLN0603-060
434103067261	MLH0603-5N6-5	433003065681	MLN0603-100
434103067281	MLH0603-8N2-5	433003065691	MLN0603-400
434103067341	MLH0603-27N-5	433003065701	MLN0603-800
433003050441	MLI0603-4S8-221	433003065711	MLN0603-121
433003050451	MLI0603-4S8-391	433003065721	MLN0603-241
433003050461	MLI0603-4S8-181	433003065731	MLN0603-301
433003050471	MLI0603-4S9-272	433003065741	MLN0603-481
433003066061	MLI0603-47N-20	433003065751	MLN0603-601
433003066071	MLI0603-68N-20	433003065761	MLN0805-060
433003066081	MLI0603-82N-20	433003065771	MLN0805-110
433003066091	MLI0603-R10-10	433003065781	MLN0805-260
433003066101	MLI0603-R12-10	433003065791	MLN0805-320
433003066111	MLI0603-R15-10	433003065801	MLN0805-600
433003066121	MLI0603-R18-10	433003065811	MLN0805-750
433003066131	MLI0603-R22-10	433003065821	MLN0805-900
433003066141	MLI0603-R27-10	433003065831	MLN0805-121
433003066151	MLI0603-R33-10	433003065841	MLN0805-151
433003066161	MLI0603-R39-10	433003065851	MLN0805-171
433003066171	MLI0603-R47-10	433003065861	MLN0805-221

433003066181	MLI0603-R56-10	433003065871	MLN0805-301
433003066191	MLI0603-R68-10	433003065881	MLN0805-401
433003066201	MLI0603-R82-10	433003065891	MLN0805-501
433003066211	MLI0603-1R0-10	433003065901	MLN0805-601
433003066221	MLI0603-1R2-10	433003065911	MLN0805-102
433003066231	MLI0603-1R5-10	433003065921	MLN0805-122
433003066241	MLI0603-1R8-10	433003065931	MLN0805-152
433003066251	MLI0603-2R2-10	433003065941	MLN1206-320
433003066261	MLI0603-2R7-10	433003065951	MLN1206-600
433003066271	MLI0603-3R3-10	433003065961	MLN1206-800
433003066281	MLI0603-3R9-10	433003065971	MLN1206-900
433003066291	MLI0603-4R7-10	433003065981	MLN1206-121
433003066301	MLI0603-5R6-10	433003065991	MLN1206-151
433003066311	MLI0603-6R8-10	433003066001	MLN1206-201
433003066321	MLI0603-8R2-10	433003066011	MLN1206-221
433003066331	MLI0603-100-10	433003066021	MLN1206-351
433003066341	MLI0805-47N-20	433003066031	MLN1206-401
433003066351	MLI0805-68N-20	433003066041	MLN1206-601
433003066361	MLI0805-82N-20	433003066051	MLN1206-122
433003066371	MLI0805-R10-10	434103065691	MLN0603-400
433003066381	MLI0805-R12-10	433003065291	MLP0603-110
433003066391	MLI0805-R15-10	433003065301	MLP0603-250
433003066401	MLI0805-R18-10	433003065311	MLP0603-400
433003066411	MLI0805-R22-10	433003065321	MLP0603-600
433003066421	MLI0805-R27-10	433003065332	MLP0603-121
433003066431	MLI0805-R33-10	433003065341	MLP0603-301
433003066441	MLI0805-R39-10	433003065351	MLP0603-501
433003066451	MLI0805-R47-10	433003065361	MLP0603-601
433003066461	MLI0805-R56-10	433003065371	MLP0603-102
433003066471	MLI0805-R68-10	433003065381	MLP0805-110
433003066481	MLI0805-R82-10	433003065391	MLP0805-170
433003066491	MLI0805-1R0-10	433003065401	MLP0805-300
433003066501	MLI0805-1R2-10	433003065411	MLP0805-600
433003066511	MLI0805-1R5-10	433003065421	MLP0805-800
433003066521	MLI0805-1R8-10	433003065431	MLP0805-121
433003066531	MLI0805-2R2-10	433003065441	MLP0805-201
433003066541	MLI080505-2R7-10	433003065451	MLP0805-301
433003066551	MLI080505-3R3-10	433003065461	MLP0805-601
433003066561	MLI080505-3R9-10	433003065471	MLP0805-102
433003066571	MLI080505-4R7-10	433003065481	MLP1206-190
433003066581	MLI080505-5R6-10	433003065491	MLP1206-320
433003066591	MLI080505-6R8-10	433003065501	MLP1206-500
433003066601	MLI080505-8R2-10	433003065511	MLP1206-700
433003066611	MLI080505-100-10	433003065521	MLP1206-800
433003066621	MLI080505-120-10	433003065531	MLP1206-101
433003066631	MLI080505-150-10	433003065541	MLP1206-301
433003066641	MLI080505-180-10	433003065551	MLP1206-601

433003066651	MLI1206-47N-20	433003065561	MLP1206-102
433003066661	MLI1206-68N-20	433003065571	MLP1206-122
433003066671	MLI1206-R10-10	433003065581	MLP1206-152
433003066681	MLI1206-R12-10	433003065591	MLP1210-600
433003066691	MLI1206-R15-10	433003065601	MLP1210-900
433003066701	MLI1206-R18-10	433003065611	MLP1806-500
433003066711	MLI1206-R22-10	433003065621	MLP1806-600
433003066721	MLI1206-R27-10	433003065631	MLP1806-800
433003066731	MLI1206-R33-10	433003065641	MLP1806-151
433003066741	MLI1206-R39-10	433003065651	MLP1812-700
433003066751	MLI1206-R47-10	433003065661	MLP1812-121
433003066761	MLI1206-R56-10	433003067781	MLPH1206-121
433003066771	MLI1206-R68-10	434103065341	MLP0603-301
433003066781	MLI1206-R82-10	434103065371	MLP0603-102
433003066791	MLI1206-1R0-10	434103065461	MLP0805-601
433003066801	MLI1206-1R2-10	434103065551	MLP1206-601

Change Description: All the multilayers, including references listed above, change their manufacturing location (from Spain to Poland) and I2NC. The change will be effective from January 2012 onwards.