



Product Discontinuance Notice - PDN 15_0041 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of All HMC852 Models

Publication Date: 01-Jun-2015

Last Time Buy Date: 01-Jun-2016

Last Time Ship Date: 01-Jun-2017

Revision Description:

Initial Release

Reason For Discontinuance

These products are being discontinued due to low or declining sales.

Comments

HMC843LC4B is recommended as a replacement. Please contact your local Analog Devices sales representative for design support.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 15_0041 Discontinued Parts Material List

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|-----------------|----------------|------------------|-----------------------|---------------------------------------|
| HMC852LC3C | HMC852 | HMC843LC4B | No | Closest alternate, Available to order |
| HMC852LC3CTR | HMC852 | HMC843LC4BTR | No | Closest alternate, Available to order |
| HMC852LC3CTR-R5 | HMC852 | HMC843LC4BTR-R5 | No | Closest alternate, Available to order |

Appendix A - PDN 15_0041 Revision History

| Rev | Publish Date | Rev Description |
|------------|---------------------|------------------------|
| Rev. - | 01-Jun-2015 | Initial Release |

Analog Devices, Inc. Proprietary Information

DocId:887 Layout Rev:2 Parent DocId:None