

Product Discontinuance Notice - PDN 19 0039 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

ADIS16405 Discontinuation

Publication Date:05-Jun-2019Last Time Buy Date:21-May-2019Last Time Ship Date:22-May-2019

Revision Description:

Initial Release

Reason For Discontinuance

Key component has been discontinued and no drop-in replacement is available.

Comments

ADI has been unable to secure a drop-in replacement for a key component, which has been obsoleted, while available supply has eroded, faster than expected. The ADIS16448 provides a similar function to the ADIS16405, but is in a different package. For those who do not need the magnetometer or barometer function, the ADIS16365 provides a suitable, pin-compatible replacement.

Supporting Documents None

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive					
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com	

PDN 19_0039 Discontinued Parts Material List							
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments			
ADIS16405BMLZ	ADIS16405	ADIS16448BMLZ		ADIS16365 offers comparable 6DOF (no magnetometer or barometer) in a pin compatible package			

Appendix A - PDN 19_0039 Revision History						
Rev	Publish Date	Rev Description				
Rev	05-Jun-2019	Initial Release				

Analog Devices, Inc. Proprietary Information

Docld:1385 Layout Rev:3 Parent Docld:None