



PCN Tracking Number: PCN_FT_024

Issue Date: 2016-10-05

Product Change Notification

Product Part Number	FT4222HQ Hi-Speed Quad SPI/I2C device	Estimated implementation date
Description of Change	Update from Rev B to Rev C to fix some issues	Oct 2016
Reason for Change	Fix existing issues and improve SPI/QSPI performance.	
Detailed Description	All issues listed below have been fixed: Issue A : Custom PID could not be changed Issue B : Abnormal response after host restart Issue C : Single mode SPI master data lost and no response issues Issue D : SPI/QSPI Performance improvement	
Impact to Data sheet	Function no change	
Benefit of Change	Issues fixed and performance improvement	
Markings to distinguish revised from:	Device date code will be changed to a "C" to indicate revision C	
Sample Availability	Oct 2016	
Risk Assessment, Fit Form and Function & reliability	Fit: Dimension have not changed. Form : Visual appearance is unchanged except for markings for rev C Function: Fix bugs listed above to improve overall performance	
PDF Download	http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_024.pdf	

Others:

For the details, please refer the Technical notes:

http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_161_FT4222H%20Errata%20Technical%20Note.pdf

and

http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_170_FT4222H%20Rev.C%20Technical%20Note.pdf