

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000963

DATE: 03-Apr-2019

PRODUCT DISCONTINUANCE NOTICE

lotice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DG418LDY+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	DS1124U-25+	N/A			Part reactivated from prior notice: M000870
Reactivation	DS1124U-25+T	N/A			Part reactivated from prior notice: M000870
Reactivation	DS1809Z-050+	N/A			Part reactivated from prior notice: M000872
Reactivation	DS1922L-F5#A22	N/A			Part reactivated from prior notice: M000963I
Reactivation	DS3881E+T&R/C	N/A			Part reactivated from prior notice: M000962I
Reactivation	DS3882E+C	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX1098CEAE+T	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX1182ECM+TD	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX1185ECM+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX1301BEUP+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX13055EETI+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX13362ATL+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX1446GHJ+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16838AUP+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16903SATB33+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX16903SATB33+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16907RAUE+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX16907RAUE+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16909RATE+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX16909RATE+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16910DASA9+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16910DASA9+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16910DATA9+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16910DATA9+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX16945TGUT+	N/A			Part reactivated from prior notice: M000963I

Reactivation	MAX16993AGJB/VY+	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX16993AGJB/VY+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX1976AETT150+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX1976AETT180+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX2171ETL+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX2180AETG+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX2180AETG+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX2680AUT+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX3318EEUP+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX3379EEUD+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX3393EEUD+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX4020EEE+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX4522ESE+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX4548EAX+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX4590EWE+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX4695EGC+	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX4835ETT25BD2+	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX4837ETT33BD3+	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX4907ELA+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX5027EUT+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX5063AASA+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX539ACSA+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX541AESA+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX5489EUD+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX5661GCB+T	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6138BEXR41+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6174BASA+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX6316LUK31BX+	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX6316LUK31BX+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX6319LHUK31A+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6381XR23D3+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6382XR26D3+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6383XR29D1+T	N/A	Part reactivated from prior notice: M000963I
Reactivation	MAX6383XR31D3+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6385XS29D3+	N/A	Part reactivated from prior notice: M000962I
Reactivation	MAX6390XS30D4+	N/A	Part reactivated from prior notice: M000962I

Reactivation	MAX6390XS30D7+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX6390XS44D4+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX6394US480D1+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX6412UK26+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6418UK31+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6423XS29+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6467XS32D3+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6706LKA+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6750KA30+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6776XKA+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6791TPSD2+T	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6834HXRD2+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6856UK23D3+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6970AUE+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX7375AXR425+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX803LEXR+T10	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX809LEUR+T10	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX8878EUK30+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX8878EUK50+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX8891EXK89+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX8896EREE+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX9247GCM+T	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX9250ECM+T	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX9395EHJ+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX9532AUB/V+	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX9532AUB/V+T	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX9650AZK+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MX7847AR+T	N/A			Part reactivated from prior notice: M000963I
Discontinuance	DS1089LU-22F+T	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	DS1089LU-A29+T	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	DS1805E-010+	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	DS1805Z-010+T&R	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	DS1844E-050+T&R	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	DS4301U-200+T&R	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX14709ENL+CNV	N/A	02-Apr-2020	02-Oct-2020	The part was not released
Discontinuance	MAX14709ENL+TCNV	N/A	02-Apr-2020	02-Oct-2020	The part was not released

Discontinuance	MAX20723EPE+	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20723EPE+T	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20724EPE+	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20724EPE+T	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20726EPE+	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20726EPE+T	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20727EPE+	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX20727EPE+T	N/A	03-Apr-2019	03-Apr-2019	The part was not released
Discontinuance	MAX44000EVKIT#	N/A	03-Apr-2019	03-Apr-2019	EVKIT is No Longer Supported
Discontinuance	MAX44000GDT+	N/A	03-Sep-2019	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX44000GDT+T	N/A	03-Sep-2019	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX44000PMB1#	MAX3750CEE+T	03-Apr-2019	03-Apr-2019	EVKIT is No Longer Supported
Discontinuance	MAX9132EVKIT+	N/A	03-Apr-2019	03-Apr-2019	EVKIT is No Longer Supported
Discontinuance	MAX9132GUP+	N/A	02-Apr-2020	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9132GUP+T	N/A	02-Apr-2020	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9134GHJ+	N/A	02-Apr-2020	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX9135GHJ+	N/A	02-Apr-2020	02-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX96911DCOAXEVKIT#	N/A	03-Apr-2019	03-Apr-2019	EVKIT is No Longer Supported