



Product Change Notification - SYST-01WULB292

Date:

03 Oct 2018

Product Category:

Motor Drivers

Affected CPNs:**Notification subject:**

Data Sheet - MCP8025A/MCP8026 3-Phase Brushless DC (BLDC) Motor Gate Driver with Power Module

Notification text:

Notification Status:Final

Description of Change:

- 1) Updated “Features” section, removed “AEC-Q100 Grade 0 Qualified”.
- 2) Updated “Applications” section.
- 3) Updated Note 2 in “AC/DC Characteristics” table.
- 4) Updated “ESD, Susceptibility, Surge and Latch-up Testing” table.
- 5) Updated Section 4.5.1 “LIN Bus Transceiver (MCP8025A)”.
- 6) Updated Section 4.5.2 “Level Translator (MCP8026)”.
- 7) Updated Section 6.4 “External MOSFET DUVLO and OCP Detection”.
- 8) Added Section 6.10 “Buck Start-up Issue” in Section 6.0 “Errata”.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 03 Oct 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

SYST-01WULB292

Microchip has released a new DeviceDoc for the MCP8025A/MCP8026 3-Phase Brushless DC (BLDC) Motor Gate Driver with Power Module of devices. If you are using one of these devices please read the document located at [MCP8025A/MCP8026 3-Phase Brushless DC \(BLDC\) Motor Gate Driver with Power Module](#).

Attachment(s):

[MCP8025A/MCP8026 3-Phase Brushless DC \(BLDC\) Motor Gate Driver with Power Module](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.



If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MCP8025A-115E/MP
MCP8025A-115E/PT
MCP8025A-115H/MP
MCP8025A-115H/MPVAO
MCP8025A-115H/PT
MCP8025AT-115E/MP
MCP8025AT-115E/PT
MCP8025AT-115H/MP
MCP8025AT-115H/MPVAO
MCP8025AT-115H/PT
MCP8026-115E/MP
MCP8026-115E/MPB3
MCP8026-115E/PT
MCP8026-115E/PTVB3
MCP8026-115H/MP
MCP8026-115H/PT
MCP8026T-115E/MP
MCP8026T-115E/MPB3
MCP8026T-115E/PT
MCP8026T-115E/PTVB3
MCP8026T-115H/MP
MCP8026T-115H/PT
MCP8026T-115H/PTVAO