

Product Change Notification - SYST-04TBVH470

Date:

08 Jun 2019

Product Category:

Ethernet PHYs

Affected CPNs:

☑

☑

☑

Notification subject:

Data Sheet - VSC8541-02 Datasheet

Notification text:

SYST-04TBVH470

Microchip has released a new DeviceDoc for the VSC8541-02 Datasheet of devices. If you are using one of these read the document located at VSC8541-02 Datasheet.

Notification Status: Final

Description of Change:

1) descriptions were updated and VeriPHY register information was deleted.

2) For functional details of the VeriPHY suite and operating instructions, see the ENT-AN0125 PHY, Integrated PHY-Switch VeriPHY - Cable Diagnostics application note.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 08 Jun 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

VSC8541-02 Datasheet

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

VSC8541XMV-02