


## Product Change Notification - SYST-09QWTC116

**Date:** 12 Mar 2018  
**Product Category:** Bluetooth Module  
**Affected CPNs:**   
**Notification subject:** Data Sheet - BM62 / BM64 Datasheet  
**Notification text:** SYST-09QWTC116

Microchip has released a new DeviceDoc for the BM62 / BM64 Datasheet of devices. If you are using one of these devices please read the document located at [BM62 / BM64 Datasheet](#).

**Notification Status:** Final

**Description of Change:**

- 1) Updated pin type for LED pins in Table 1-2 and Table 1-3 for Device Overview
- 2) Updated Under Voltage Protection (Software dependent UVP) section
- 3) Added 5.1 "Power Supply", 5.2.1 "Device FW Upgrade (DFU)" and 5.2.1.1 "Enter BT Module/MCU DFU mode". Added Figure 5-1, Figure 5-9 and Figure 5-10. Updated Figure 5-4, Figure 5-8, Figure 5-20 and Table 5-1 in Application Information
- 4) Updated Table 8-2 in Electrical Characteristics

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 12 March 2018

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):** [BM62 / BM64 Datasheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

BM62SPKS1MC2-0001AA

BM62SPKA1MC2-0001AA

BM64SPKS1MC2-Y003AA

BM64SPKS1MC2-0001AA

BM64SPKS1MC1-0001AA

BM64SPKA1MC2-0001AA

BM64SPKA1MC1-0001AA