



Product Change Notification - SYST-12VGCZ416

Date:

15 Apr 2019

Product Category:

Ultrasound MOSFET Drivers

Affected CPNs:**Notification subject:**

Data Sheet - MD1711 High-Speed Integrated Ultrasound Driver IC Data Sheet

Notification text:

SYST-12VGCZ416

Microchip has released a new DeviceDoc for the MD1711 High-Speed Integrated Ultrasound Driver IC Data Sheet of devices. If you are using one of these devices please read the document located at [MD1711 High-Speed Integrated Ultrasound Driver IC Data Sheet](#).

Notification Status: Final**Description of Change:**

- 1) Converted Supertex Doc# DSFP-MD1711 to Microchip DS20005740A
- 2) Changed package marking formats
- 3) Changed the quantity of the 48-lead LQFP FG M931 media type from 3000/Reel to 1000/Reel
- 4) Changed the quantity of the 48-lead VQFN K6 package from 250/Tray to 260/Tray
- 5) Changed the quantity of the 48-lead VQFN K6 M933 media type from 2000/Reel to 3000/Reel
- 6) Made minor text changes throughout the document

Impacts to Data Sheet: None**Reason for Change:** To Improve Manufacturability**Change Implementation Status:** Complete**Date Document Changes Effective:** 15 Apr 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A**Attachment(s):**

[MD1711 High-Speed Integrated Ultrasound Driver IC Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MD1711DB2

MD1711FG-G

MD1711FG-G-M931

MD1711K6-G

MD1711K6-G-M933