



Product Change Notification - SYST-14XIOX169

Date:	15 Jun 2017
Product Category:	USB to Ethernet Controllers
Affected CPNs:	 
Notification subject:	Data Sheet - LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII Data Sheet Document Revision
Notification text:	SYST-14XIOX169

Microchip has released a new DeviceDoc for the LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII of devices. If you are using one of these devices please read the document located at [LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII](#).

Notification Status: Final

Description of Change: 1) Removed +2.5V from Switcher Input Voltage description for Table 3-2, Pin Assignments 2) Changed +2.5-3.3V to +3.3V in Figure 4-1, Power Connection Diagram 3) Updated Section 15.4, Current Consumption and Power Dissipation in Section 15.0, Operational Characteristics 4) Updated ordering code information for extended automotive option for Product Identification System

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 15 June 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN7801-V/9JXVAO
LAN7801-V/9JX
LAN7801T-V/9JXVAO
LAN7801T-V/9JX
LAN7801T-I/9JXVAO
LAN7801T-I/9JX
LAN7801T/9JX
LAN7801-I/9JXVAO
LAN7801-I/9JX
LAN7801/9JX