## Product Change Notification - SYST-15LQVJ019

Date: 21 Feb 2018

8-bit PIC Microcontrollers **Product Category:** 

Affected CPNs:

Notification subject: ERRATA - PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification

Notification text:

SYST-15LQVJ019

Microchip has released a new DeviceDoc for the PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification.

**Notification Status:** Final

**Description of Change:** 1) Added Silicon Revision A2. 2) Added 3.4 Baud Rate Generator Speed Select 3) 3.5 Stop Bit Interrupt Flag – renumbered sections. 4) Other minor corrections.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity Change Implementation Status: Complete Estimated First Ship Date: 15 April 2018

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change

parts.

Markings to Distinguish Revised from Unrevised Devices: Traceability Code

Attachment(s): PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification

Please contact your local Microchip sales office with questions or concerns regarding this notification.

#### **Terms and Conditions:**

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

### SYST-15LQVJ019 - ERRATA - PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification

#### Affected Catalog Part Numbers (CPN)

PIC18LF25K42T-I/SS

PIC18LF25K42T-I/SO

PIC18LF25K42T-I/MV

PIC18LF25K42T-I/ML

PIC18LF25K42-I/SS

PIC18LF25K42-I/SP

PIC18LF25K42-I/SO

PIC18LF25K42-I/MV

PIC18LF25K42-I/ML

PIC18LF25K42-E/SS

PIC18LF25K42-E/SP

PIC18LF25K42-E/SO

PIC18LF25K42-E/MV

PIC18LF25K42-E/ML

PIC18F25K42T-I/SS

PIC18F25K42T-I/SO

PIC18F25K42T-I/MV

PIC18F25K42T-I/ML

PIC18F25K42T-E/SSVAO

PIC18F25K42-I/SS

PIC18F25K42-I/SP

PIC18F25K42-I/SO

PIC18F25K42-I/MV

PIC18F25K42-I/ML

PIC18F25K42-E/SSVAO

PIC18F25K42-E/SS

PIC18F25K42-E/SPREL

PIC18F25K42-E/SP

PIC18F25K42-E/SO

PIC18F25K42-E/MV

PIC18F25K42-E/ML

PIC18LF24K42T-I/SS

PIC18LF24K42T-I/SO

PIC18LF24K42T-I/MV

PIC18LF24K42T-I/ML

PIC18LF24K42-I/SS

PIC18LF24K42-I/SP

PIC18LF24K42-I/SO

PIC18LF24K42-I/MV

PIC18LF24K42-I/ML

PIC18LF24K42-E/SS

PIC18LF24K42-E/SP

PIC18LF24K42-E/SO

PIC18LF24K42-E/MV PIC18LF24K42-E/ML

PIC18F24K42T-I/SS

PIC18F24K42T-I/SO

Date: Tuesday, February 20, 2018

# SYST-15LQVJ019 - ERRATA - PIC18(L)F24/25K42 Silicon Errata and Data Sheet Clarification PIC18F24K42T-I/MV PIC18F24K42T-I/ML PIC18F24K42-I/SS PIC18F24K42-I/SP PIC18F24K42-I/SO PIC18F24K42-I/MV PIC18F24K42-I/ML PIC18F24K42-E/SS PIC18F24K42-E/SP PIC18F24K42-E/SO PIC18F24K42-E/MV PIC18F24K42-E/ML

Date: Tuesday, February 20, 2018