



## Customer Information Notification

2017080171

**Issue Date:** 16-Aug-2017  
**Effective Date:** 13-Nov-2017

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online



# QUALITY

### Management Summary

We are extending the last time buy date for SA58637BS and TDA7052AT/N2 from 30 June 2017 to 31 December 2018

### Change Category

- |  |   |   |   |   |
|--|---|---|---|---|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process   | <input type="checkbox"/> Product Marking                      | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                         |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification             | <input type="checkbox"/> Test Process   | <input type="checkbox"/> Errata                         |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location  | <input checked="" type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |

Last Time Buy Date  
Extension SA58637BS  
and TDA7052AT/N2

## Information Notification

This is to inform customers that we are extending the last time buy (LTB) and last time delivery(LTS) date for the below parts, issued on DN notification 2016009003DN, discontinued due to NXP exit from the ASMC wafer fab.

LTB is extended from 30-Jun-2017 to 31 December 2018, and Last time Delivery date from 31-Dec-2017.to 30 June 2019

SA58637BS,118  
TDA7052AT/N2,112  
TDA7052AT/N2,118

### Why do we issue this Information Notification

With this notification we want to inform our customers that LTB and LTS dates have been extended for above mentioned parts

### Identification of Affected Products

Product identification does not change

## Impact

no impact to the product's functionality anticipated.

## Additional information

Affected products and sales history information: see attached file

## Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**Name** Iris Brinck

**Position** Commercial Marketing Manager

**e-mail address** iris.brinck@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

## About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[View Notification](#)

[Subscription](#)

[Support](#)

[NXP](#) | [Privacy Policy](#) | [Terms of Use](#)

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

### Affected Part Numbers

TDA7052AT/N2,118

SA58637BS,118

SA58637BS,118

TDA7052AT/N2,118