

Product Bulletin
Document #: PB21477Z Issue Date: 13 October 2016

Title of Change:	Update of Product Data Sheet for the T092 Package to indicate correct Date Code Marking for the listed IC Products.	
Effective date:	13 October 2016	
Contact information:	Contact your local ON Semiconductor Sales Office or <a href="mailto:alan.garlington@onsemi.com">alan.garlington@onsemi.com</a>	
Type of notification:  ON Semiconductor will consider this change accepted.		oted.
Change category:	☐ Wafer Fab Change ☐ Assembly Change	☐ Test Change ☐ Other: Marking Date Code
Change Sub-Category(s):  Manufacturing Site Change, Manufacturing Process Change		<ul><li>□ Datasheet/Product Doc change</li><li>□ Shipping/Packaging/Marking</li><li>□ Other: <u>Date Code Marking Correction</u></li></ul>
Sites Affected: Not App  ☐ All site(s) ☐ not app		☐ External Foundry/Subcon site(s)
Description and Purpose:		
The style of the Product date codes actually being marked on the IC T092 Products does not match what is stated in the Product Data sheets.		
The product data sheets will be corrected to reflect the actual style being used.		
Example of a current data sheet date code:		
MC78L zzASP ALYWW  1 2 3  zz = 05, 08, 09, 12, 15, 18 or 24  A = Assembly Location L = Wafer Lot Y = Year WW = Work Week		
ALYWW style of code has never been used on these products due to insufficient space on the package.  ALYW style has actually been in use for many years.		
ALTER STATE THIS deciding Decir in disc for many years.		

Page 1 of 2 TEM001094 Rev. E



## **Product Bulletin**

Document # : PB21477Z Issue Date: 13 October 2016

## **List of Affected Standard Parts:**

NCP431ACLPRAG

NCP431AILPRAG

NCP431AVLPG

NCP431AVLPRAG

NCV2931AZ-5.0G

.....

NCV2931AZ-5.0RAG

NCV317LBZG

NCV317LBZRAG

NCV33064P-5RAG

NCV33064P-5RPG

NCV78L05ABPG

NCV78L05ABPRAG

NCV78L05ABPREG

NCV78L05ABPRMG

NCV78L05ABPRPG

NCV78L12ABPG

NCV78L24ABPRPG

TEM001094 Rev. E Page 2 of 2